

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 05 Jan 2021

Preliminary Advice

Insured Vehicle No : GBE6533P
TP Vehicle No : GBB5942P
Make : TOYOTA DYNA 100 MANUAL
Date of Inspection : 04/01/2021
Inspection At : CARZ AUTO SERVICES PTE LTD - WOODLANDS (HQ)
NO 61, WOODLANDS INDUSTRIAL PARK E9, #04-04 E9 PREMIUM SINGAPORE 757047
SINGAPORE 757047

Accident Date : 29/12/2020
Assignment Date : 04/01/2021
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,023.25
Revised Amount	:S\$	2,369.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,369.28

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.