



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2105352

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 01/08/2021
Reference CC4/FCI21000094/Gra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJH 9830B
Insured Veh. SHB 2151D
Claim No. D21000065MFSH
Policy No. D-20094921MFSH
Accident Date 30/12/2020
Inspection Date 04/01/2021

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21000094/Gra3q2 Date: 01/08/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 2151D	Veh. Inspected	SJH 9830B
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D21000065MFSH	Excess (\$)	0.00
	Assign From	ERIC	Assign Date	04/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN SERENA 1.2	c.c	1198
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JN1EBAC27Z0000101	Colour	WHITE
	Odometer	13161 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R16	DUNLOP	8 mm
	L/H Front Tyre	195/60 R16	DUNLOP	8 mm
	R/H Rear Tyre	195/60 R16	DUNLOP	8 mm
	L/H Rear Tyre	195/60 R16	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/12/2020	Inspection Date	04/01/2021
	Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 9830B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE ,RR BUMPER (N)	CRACKED	1,414.00	1,414.00
1	EMBLEM -REAR E POWER (N)	NOT NECESSARY	94.40	-
1	EMBLEM -REAR HIGHWAY STAR (N)	NOT NECESSARY	50.90	-
1	DOOR BACK (N)	NOT NECESSARY	1,742.00	-
1	ORNAMENT -REAR EMBLEM (N)	NOT NECESSARY	79.90	-
1	RR PANEL -LWR (N)	NOT NECESSARY	215.00	-
	LESS 20% DISCOUNT		-719.24	-282.80
			2,876.96	1,131.20
	<u>SPECIAL NETT ITEMS</u>			
2	COVER REVERSE SENSOR CENTER (SN)	NECESSARY	145.00	145.00
1	COVER REVERSE SENSOR BRACKET RH (SN)	NECESSARY	96.30	96.30
1	COVER REVERSE SENSOR BRACKET LH (SN)	NECESSARY	96.30	96.30
4	EYES SENSOR -REVERSE (SN)	NOT NECESSARY	360.00	-
			697.60	337.60
	<u>LABOUR</u>			
	REPLACE REVERSE SENSOR ,NECESSARY ADJUSTMENT & FUNCTION TEST .		55.00	55.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	300.00	-
	REPAIR /REPLACE REAR BUMPER ,END PANEL ,RH FENDER ,AND TAILGATE .		1,560.00	390.00
	RESPRAY REAR BUMPER ,END PANEL ,TAILGATE & REAR RH FENDER .		1,000.00	250.00
	REMOVE/REFIX REAR TRIMS ,GARNISH AND SEAT TO FACILITATE REPAIR .	NOT NECESSARY	290.00	-
	CHECK ALL LIGHTINGS AFTER REPAIR TO REAR PORTION .	NOT NECESSARY	48.00	-
			3,253.00	695.00
	GRAND TOTAL		6,827.56	2,163.80



RECOMMENDED COST OF REPAIRS			2,163.80
-----------------------------	--	--	----------

Report Ref No. CC4/FCI21000094/Gra3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 9830B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 9830B

RE-INSPECTION

