

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 170/IC/TCAC/SAY/2020
DATE : 30-DEC-2020

FIRST CAPITAL INSURANCE LTD REFER MS FIRST
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848 / 68543466
FAX : 65073849
ATTN:MOTOR CLAIM MANAGER(MARY 68543461)

OWNER'S NAME : M/S MOTORIMAGE ENTERPRISES PTE LTD
ADDRESS : 911 BUKIT TIMAH ROAD
S(589622)
TELEPHONE NO : 92299633 MR TEO

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 999993946/100880804-00003
VEHICLE NO : SJH9830B
MODEL CODE : EDWARW9C27HWA-----
MODEL/YEAR : NISSAN SERENA E-POWER 1.2 HIGHWAY STAR MY2019
ENGINE NO : HR12073858K-C27FL
CHASSIS NO : JN1EBAC27Z0000101
MILEAGE : 12754 KM
DATE IN : 30/12/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 30/12/2020

OCCLINIC PTE LTD
JENKINS ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJH9830B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	/
2	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	?
3	ZZ/001	CONDUCT TP CLAIM 1ST CAP DATE:30/12/2020 TIME:1245 LOCATION: TRAFFIC LIGHT JUNCTION GRANGE ROAD		
4	ZZ/002	REPAIR/REPLACE REAR BUMPER, END PANEL, RH FENDER, AND TAILGATE 390	1560.00	390
5	ZZ/003	RESPRAY REAR BUMPER, END PANEL, TAILGATE & REAR RH FENDER 250	1000.00	250
6	ZZ/004	REMOVE/REFIX REAR TRIMS, GARNISH AND SEAT TO FACILITATE REPAIR	290.00	?
7	ZZ/005	CHECK ALL LIGHTINGS AFTER REPAIR TO REAR PORTION	48.00	?
8	ZZ/006	QC & CONSULT CHECK		
9	ZZ/007	CARWASH AND VACUUM		
TOTAL LABOUR CHARGES			3253.00	

CLINIC PTE LTD
G KEE ROAD
APORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJH9830B

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	COVER REVERSE SENSOR CENTER 2 PCS	28533-5ZA0A			145.00
2	COVER REVERSE SENSOR BRACKET RH	28533-5TT1D			96.30
3	COVER REVERSE SENSOR BRACKET LH	28533-5TT0D			96.30
4	SENSOR-REVERSE 4 EYES ?	SENSOR			360.00
5	FACE-RR BUMPER / CAA	85022-5TT6H	1414.00		
6	EMBLEM-REAR E POWER X	90892-5TL0A	94.40		
7	EMBLEM-REAR HIGHWAY STAR X	90897-5TA0A	50.90		
8	DOOR BACK X	K010M-5TA0A	1742.00		
9	ORNAMENT-REAR EMBLEM X	90886-5TA0B	79.90		
10	RR PANEL-LWR ?	79120-5TT0A	215.00		
SUB TOTAL			3596.20	0.00	697.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			719.24	0.00	0.00
GRAND TOTAL			2876.96	0.00	697.60
OVERALL TOTAL			3574.56		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ARY OF ESTIMATE FOR VEHICLE REGN NO SJH9830B

TOTAL LABOUR CHARGES	3253.00
TOTAL SPARE PARTS CHARGES	3574.56
GRAND TOTAL	6827.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Guo Qiang - 82880282
04/1/2021

before paint photos.

Guo Qiang @lkkauto.com.

3 Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: