



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN : SALIHA SYED YUSOFF			Ref: CS3/AIG20008743/Eqd3e2-1 Date: 07/01/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 1578H	Veh. Inspected	SCM 66G	
Policy No.	0999993854	Coverage (\$)	0.00	
Claim No.	8905538599SG	Excess (\$)	0.00	
Assign From	SALIHA SYED YUSOFF	Assign Date	04/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	ACR500165914	Colour	BLACK	
Odometer	80101 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	YOKOHAMA	4 mm	
L/H Front Tyre	245/40 R19	YOKOHAMA	4 mm	
R/H Rear Tyre	245/40 R19	YOKOHAMA	4 mm	
L/H Rear Tyre	245/40 R19	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2020	Inspection Date	21/08/2020	
Survey held at	TRI KING AUTO SOLUTIONS PTE LTD 53 UBI AVENUE 1 #01-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	