



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th December 2020
1st Capital-TP

SLR 6784 U TOYOTA SIENTA

Spare Parts	1	Rear boot. ✓
	1	Rear boot logo. ✓
	1	Rear boot centre garnish. ✓
	1	Rear boot inner garnish. ?
	1	Set rear boot inner garnish clips. ?
	1	Set rear windscreen mouldings. ✓
	2	Rear tail lights. @\$344.30/- X - RH
	2	Rear boot reflectors. @\$109/- ?
	1	Rear support panel. ?
	1	Rear inner support panel. ?
	1	Rear panel inner garnish. ?
	1	Set rear panel inner garnish clips. ?
	1	Rear spare wheel base. R
	1	Rear spare wheel base cover. ✓
	2	Rear fender cowlings. @\$61/- X
	2	Sets rear fender cowlings clips. \$55/- X
	1	Rear bumper. ✓
	2	Rear bumper brackets. @\$105/- ?
	1	Set rear bumper clips. ✓
	2	Rear bumper side retainers. @\$70.50/- ?
	1	Rear lower bumper. ✓
	2	Rear bumper sides. @\$129.10/- X R
	2	Rear bumper side mouldings. @\$125/- ?
	2	Set rear bumper side moulding clips. @ \$33/- ?
	2	Rear bumper reflectors. @\$59.80/- X
	1	Rear windscreen inner seal. ✓
	1	Rear windscreen sealant. ✓
	1	Rear number plate. ✓

SS
1131.90 ✓ bt
72.30 ✓ nel
207.90 ✓ de
138.00 X nn
28.00 X nn
136.50 ✓ nel
LHXnn. 688.60 344.30 RH-art
218.00 X nn
433.60 ✓ bt
696.30 ✓ bt
147.50 ✓ de
36.00 X nn
R X 698.70 X
466.40 ✓ X
122.00 X nn
110.00 X
318.20 ✓ de
210.00 X nn
66.00 ✓ nel
141.00 X X
190.00 X nn
258.20 X
250.00 X
66.00 X
119.60 X
42.00 Snet nel
50.00 Snet nel
4555.00 Snet bt

7097.70
Less 25% (1737.68)

Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear lower member, rt rear fender, left rear fender, renew rear boot, rear support panel, rear lights, rear reflectors, rear bumper and assembly.
	To respray damaged parts.
	To remove rear garnishes, carpets, upholstery, centre seats, rear seats, side covers to facilitate repairs and assembly.
	To remove, replace rear windscreen.
	To reseal joints, reinsulate, anti rust panels and assembly.

5360.02
1200.00 800

1200.00 ~~800~~ - (1000) - Fuel panel & inner panel
150.00 60

150.00 120
120.00 60

8180.02

Foley.



樹發汽車修理廠 SHU FATT AUTO WORKS

94235480

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th December 2020

Supplementary
MS First Capital-TP

SLR 6784 U TOYOTA SIENTA

Spare Parts	1	Tail gate luggage compartment <i>de ✓</i>	S\$
	1	Electrical Key sensor. <i>mis / mis</i>	432.40
	1	Rear bumper center garnish. <i>and ✓</i>	105.00
			190.00
			<hr/>
			727.40
		Less 25%	(181.85)
			<hr/>
			545.55

Form
11/01/2021

Parts: 4281.90 ✓
-55%: (1070.48)
3211.43 ✓
Net: 1370.00 ✓
3348.43
labour: 2040.00 ✓
\$ 5388.43
7 days. #

Always.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th December 2020
1st Capital-TP

Suppl^u

SLR 6784 U TOYOTA SIENTA

Spare Parts			SS
1	Rear boot.	<i>bt ✓</i>	
1	Rear boot logo.	<i>ne ✓</i>	
1	Rear boot centre garnish.	<i>de ✓</i>	
1	Rear boot inner garnish.	<i>? X</i>	
1	Set rear boot inner garnish clips.	<i>? ✓</i>	
1	Set rear windscreen mouldings.	<i>ne ✓</i>	
2	Rear tail lights.	<i>X - RH ✓</i>	
2	Rear boot reflectors.	<i>? ✓</i>	
1	Rear support panel.	<i>? ✓</i>	
1	Rear inner support panel.	<i>? ✓</i>	
1	Rear panel inner garnish.	<i>? ✓ - broken</i>	
1	Set rear panel inner garnish clips.	<i>? ✓ - rec</i>	
1	Rear spare wheel base.	<i>R ✓ - broken</i>	
1	Rear spare wheel base cover.	<i>X</i>	
2	Rear fender cowlings.	<i>X</i>	
2	Sets rear fender cowlings clips.	<i>X</i>	
1	Rear bumper.	<i>de ✓</i>	
2	Rear bumper brackets.	<i>? ✓</i>	
1	Set rear bumper clips.	<i>ne ✓</i>	
2	Rear bumper side retainers.	<i>? ✓</i>	
1	Rear lower bumper.	<i>de ✓</i>	
2	Rear bumper sides.	<i>RP</i>	
2	Rear bumper side mouldings.	<i>? ✓</i>	
2	Set rear bumper side moulding clips.	<i>? ✓</i>	
2	Rear bumper reflectors.	<i>X</i>	
1	Rear windscreen inner seal.	<i>ne ✓</i>	42.00 Snet
1	Rear windscreen sealant.	<i>ne ✓</i>	50.00 Snet
1	Rear number plate.	<i>bt ✓</i>	45 55.00 Snet

Less

Labour	To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear lower member, rt rear fender, left rear fender, renew rear boot, rear support panel, rear lights, rear reflectors, rear bumper and assembly.	1200.00	<i>800</i>
	To respray damaged parts.	1200.00	<i>1000</i>
	To remove rear garnishes, carpets, upholstery, centre seats, rear seats, side covers to facilitate repairs and assembly.	150.00	<i>800</i>
	To remove, replace rear windscreen.	150.00	<i>60</i>
	To reseal joints, reinsulate, anti rust panels and assembly.	120.00	<i>120</i>

Tanph 97415749
WP 5/1/21 @ 1230 06day
1/5 Resumy after repair
Tanph @ 11hant. wu.

Kunho 205/50ZR16
NSP170-7028727
68076

Kunho
205/50ZR16.