



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo  
30<sup>th</sup> December 2020  
1<sup>st</sup> Capital-TP

SLR 6784 U TOYOTA SIENTA

Spare Parts			SS
1	Rear boot.	bt ✓	
1	Rear boot logo.	na ✓	
1	Rear boot centre garnish.	de ✓	
1	Rear boot inner garnish.	?	
1	Set rear boot inner garnish clips.	?	
1	Set rear windscreen mouldings.	na ✓	
2	Rear tail lights.	x	
2	Rear boot reflectors.	?	
1	Rear support panel.	?	
1	Rear inner support panel.	?	
1	Rear panel inner garnish.	?	
1	Set rear panel inner garnish clips.	?	
1	Rear spare wheel base.	R ✓	
1	Rear spare wheel base cover.	x	
2	Rear fender cowlings.	x	
2	Sets rear fender cowlings clips.	x	
1	Rear bumper.	de ✓	
2	Rear bumper brackets.	?	
1	Set rear bumper clips.	na ✓	
2	Rear bumper side retainers.	?	
1	Rear lower bumper.	de ✓	
2	Rear bumper sides.	R ✓	
2	Rear bumper side mouldings.	?	
2	Set rear bumper side moulding clips.	?	
2	Rear bumper reflectors.	x	
1	Rear windscreen inner seal.	na ✓	42.00 Snet
1	Rear windscreen sealant.	na ✓	50.00 Snet
1	Rear number plate.	bt ✓	45 55.00 Snet

Less

Labour

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, rear lower member, rt rear fender, left rear fender, renew rear boot, rear support panel, rear lights, rear reflectors, rear bumper and assembly.

1200.00 800

To respray damaged parts.

1200.00 800

To remove rear garnishes, carpets, upholstery, centre seats, rear seats, side covers to facilitate repairs and assembly.

150.00 60

To remove, replace rear windscreen.

150.00 120

To reseal joints, reinsulate, anti rust panels and assembly.

120.00 60

Tan Kah 97415749

WP 5/1/21 @ 1230 06 days

1/3 Respray after repair  
Tan Kah @ 11hamp. w.m.

16m ho  
205/50R16

Kumho 205/50ZR16  
NSP170- 7028727  
68076