



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104950

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/07/2021
Reference CC4/FCI21000101/Qra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBF 7739B
Insured Veh. SH 2656C
Claim No. D20005076MFSH
Policy No. D-20094922MFSH
Accident Date 09/12/2020
Inspection Date 05/01/2021

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21000101/Qra3q2	
			Date: 14/07/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 2656C	Veh. Inspected	FBF 7739B	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20005076MFSH	Excess (\$)	0.00	
Assign From	CHRIS LIM	Assign Date	04/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA T135	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	5YP303263	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/30-17	DUNLOP	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	90/30-17	DUNLOP	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2020	Inspection Date	05/01/2021	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) 39 WOODLANDS CLOSE #01-12 MEGA @ WOODLANDS SINGAPORE 737856			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 7739B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER	CRUMPLED	170.00	105.00
1	FRONT FORK LH	SERVICEABLE	190.00	-
1	FRONT SIDE LAMP LH	CRUMPLED	230.00	90.00
1	FRONT SIDE LAMP RH	SERVICEABLE	230.00	-
1	FRONT WHEEL RIM	SCRATCHED	200.00	200.00
1	FRONT FAIRING	CRUMPLED	380.00	180.00
1	FRONT FAIRING INNER FAIRING	CRUMPLED	350.00	175.00
1	FRONT SIDE FAIRING LH	MISSING	130.00	130.00
1	FRONT SIDE FAIRING INNER GARNISH LH	MISSING	65.00	65.00
1	FRONT HEADLAMP	SCRATCHED	365.00	365.00
1	FRONT HEADLAMP FAIRING	SCRATCHED	290.00	150.00
1	FRONT HEADLAMP INNER FAIRING	SERVICEABLE	265.00	-
1	FRONT SIDE MIRRIR LH	SCRATCHED	65.00	65.00
1	FRONT SIDE MIRRIR RH	MISSING	65.00	65.00
1	FRONT BALANCER LH	SCRATCHED	12.00	12.00
1	FRONT BALANCER RH	NECESSARY	12.00	12.00
1	FRONT CLUTCH LEBER LH	BENT	25.00	25.00
1	FRONT BRAKE LEVER RH	SERVICEABLE	25.00	-
1	FRONT SPEEDOMETER	SERVICEABLE	480.00	-
1	CENTRE FAIRING	SERVICEABLE	155.00	-
1	CENTRE SIDE FAIRING LH	SERVICEABLE	105.00	-
1	FRONT FOOT GEAR LEVER LH	BENT	85.00	85.00
1	FRONT FOOT REST LH	BENT	45.00	45.00
1	FRONT FOOT REST BRACKET LH	SERVICEABLE	165.00	-
1	ENGINE CRANK CASE COVER LH	SERVICEABLE	177.00	-
1	ENGINE CRANK CASE COVER GASKET	SERVICEABLE	25.00	-
1	REAR FOOT REST LH	SCRATCHED	45.00	45.00
1	REAR FOOT REST BRACKET LH	SCRATCHED	165.00	165.00
1	REAR FAIRING LH	SCRATCHED	330.00	180.00
1	REAR TAILLAMP	SCRATCHED	347.00	150.00
1	FRONT FAIRING LOGO	NECESSARY	55.00	55.00

Report Ref No. CC4/FCI21000101/Qra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-524.80	-236.40
			4,723.20	2,127.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	FRONT FAIRING STICKER (SN)	NECESSARY	70.00	50.00
1	FRONT SIDE FAIRING STICKER LH (SN)	NECESSARY	65.00	50.00
1	CENTRE INNER BOX (SN)	SCRATCHED	85.00	85.00
1	ENGINE OIL (SN)	SERVICEABLE	75.00	-
1	REAR FAIRING STICKER LH (SN)	NECESSARY	70.00	50.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	35.00	-
			435.00	270.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS.		40.00	20.00
	TO CONDUCT WHEEL BALANCING.		60.00	20.00
	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE .		220.00	70.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS,TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		450.00	150.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	NOT NECESSARY	350.00	-
			1,120.00	260.00
GRAND TOTAL			6,278.20	2,657.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CC4/FCI21000101/Qra3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 7739B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBF 7739B

RE-INSPECTION

