

Estimate Report

12/31/2020

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTMG/TP/2012/009
Policy No:	PNMC2020-00001583	Date of Loss:	09/12/2020
Vehicle Reg. No.:	FBF7739B	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SH2656C
Any Injuries?	yes	Contact No:	96300401
Insured/Claimant:	MOHAMMED MOKTAR BIN YUSOFF	Driver:	MUHAMMAD AMZAR BIN MOHAMMED MOKTAR

Make/Model:	Yamaha, T135	Vehicle Reg. Date:	26/11/2011
Vehicle Colour:		Engine Number:	
Chassis No:	5YP303263	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss Side Swipe
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		4,723.20
Miscellaneous Items		435.00
Labour		770.00
Paintwork Labour		350.00
Towing		0.00
Gross Total(\$\$):		6,278.20
GST 7.00%(\$\$):		439.47
Nett Amount(\$\$):		6,717.67

This claim is handled by: Sky Toh T C

Estimate Report

12/31/2020

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : FIRST CAPITAL INSURANCE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/2012/009
Policy No:	PNMC2020-00001583	Date of Loss:	09/12/2020
Vehicle Reg. No.:	FBF7739B	Driveable?	yes
Driver Age:		Third Party Vehicle No.:	SH2656C
Any Injuries?	yes	Contact No:	96300401
Insured/Claimant:	MOHAMMED MOKTAR BIN YUSOFF	Driver:	MUHAMMAD AMZAR BIN MOHAMMED MOKTAR

Make/Model:	Yamaha, T135	Vehicle Reg. Date:	26/11/2011
Vehicle Colour:		Engine Number:	
Chassis No:	5YP303263	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss Side Swipe
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	4,723.20
Miscellaneous Items	435.00
Labour	770.00
Paintwork Labour	350.00
Towing	0.00
Gross Total(S\$):	6,278.20
GST 7.00%(S\$):	439.47
Nett Amount(S\$):	6,717.67

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT FENDER / CRU	170.00 105	-10.00	153.00
2	1	FRONT FORK LH X SVC	190.00 X	-10.00	171.00
3	1	FRONT SIDE LAMP LH / CRU	230.00 90	-10.00	207.00
4	1	FRONT SIDE LAMP RH 2 X SVC	230.00 X	-10.00	207.00
5	1	FRONT WHEEL RIM X / SCR	200.00 /	-10.00	180.00
6	1	FRONT FAIRING / CRU	380.00 186	-10.00	342.00
7	1	FRONT FAIRING INNER FAIRING / CRU	350.00 175	-10.00	315.00
8	1	FRONT SIDE FAIRING LH / NIB	130.00 /	-10.00	117.00
9	1	FRONT SIDE FAIRING INNER GARNISH LH / MIB	65.00 /	-10.00	58.50
10	1	FRONT HEADLAMP / SCR	365.00 /	-10.00	328.50
11	1	FRONT HEADLAMP FAIRING / SCR	290.00 150	-10.00	261.00
12	1	FRONT HEADLAMP INNER FAIRING X SVC	265.00 X	-10.00	238.50
13	1	FRONT SIDE MIRROR LH / SCH	65.00 /	-10.00	58.50
14	1	FRONT SIDE MIRROR RH X / MIB	65.00 /	-10.00	58.50
15	1	FRONT BALANCER LH / SCH	12.00 /	-10.00	10.80
16	1	FRONT BALANCER RH / NRC	12.00 /	-10.00	10.80
17	1	FRONT CLUTCH LEVER LH / BT	25.00 /	-10.00	22.50
18	1	FRONT BRAKE LEVER RH X SVC	25.00 X	-10.00	22.50
19	1	FRONT SPEEDOMETER X SVC	480.00 X	-10.00	432.00
20	1	CENTRE FAIRING 2 X SVC	155.00 X	-10.00	139.50
21	1	CENTRE SIDE FAIRING LH 2 X SVC	105.00 X	-10.00	94.50
22	1	FRONT FOOT GEAR LEVER LH / BT	85.00 /	-10.00	76.50
23	1	FRONT FOOT REST LH / BT	45.00 /	-10.00	40.50
24	1	FRONT FOOT REST BRACKET LH 2 X SVC	165.00 X	-10.00	148.50
25	1	ENGINE CRANK CASE COVER LH X SVC	177.00 X	-10.00	159.30
26	1	ENGINE CRANK CASE COVER GASKET X SVC	25.00 X	-10.00	22.50
27	1	REAR FOOT REST LH / SCR	45.00 /	-10.00	40.50
28	1	REAR FOOT REST BRACKET LH / SCR	165.00 /	-10.00	148.50
29	1	REAR FAIRING LH / SCR	330.00 180	-10.00	297.00
30	1	REAR TAILLAMP / SCR	347.00 150	-10.00	312.30
31	1	FRONT FAIRING LOGO / NRC	55.00 /	-10.00	49.50

Total Parts (\$\$) 4,723.20

2,364
-10%
2,127.60

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE / BT	35.00 /	0.00	35.00
2	1	FRONT FAIRING STICKER / NRC	70.00 50	0.00	70.00
3	1	FRONT SIDE FAIRING STICKER LH / NRC	65.00 50	0.00	65.00
4	1	CENTRE INNER BOX / SCR	85.00 /	0.00	85.00
5	1	ENGINE OIL X SVC	75.00 X	0.00	75.00
6	1	REAR FAIRING STICKER LH / NRC	70.00 50	0.00	70.00
7	1	REAR NUMBER PLATE X SVC	35.00 X	0.00	35.00

Sub Total (\$\$) 435.00

270.

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace	40.00	0.00	40.00

20

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
2	1	Damaged Parts.			
		To Conduct Wheel Balancing	60.00	0.00	60.00 ²⁰
3	1	To Dismantle and Refit Front Undercarriage.	220.00	0.00	220.00 ⁷⁰
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	0.00	450.00 ¹⁵⁰

260

Gross Labour Cost (S\$) 770.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	350.00	0.00	350.00 ^X

Gross Labour Cost (S\$) 350.00

< END OF ESTIMATES >

Repair day - 3 days.

LIS

After paint photo.

Sun Pin (Lkk)

05/01/2021

TP without prejudice.

2,127.60

270

260

2,657.60

- 20%

2,126.08

LIS

\$2,100

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work is subject to confirmation by the Insurance Company

Acknowledged by Repairer

Signature:

Date: