

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2101-001

DATE : 4-Jan-2021

POLICY NO. : AVIVA

VEHICLE REG. NO. : SLS2057G

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 580.00	\$ 580.00
2	Front Bumper Clip	10	\$ 5.00	\$ 50.00
3	Front Bumper Retainer RH	1	\$ 40.00	\$ 40.00
4	Front Bumper Retainer LH	1	\$ 40.00	\$ 40.00
5	Front Reinforcement	1	\$ 700.00	\$ 700.00
6	Front Sponge/absorber	1	\$ 180.00	\$ 180.00
7	Front License Garnish	1	\$ 40.00	\$ 40.00
8	Front Grille Assy	1	\$ 480.00	\$ 480.00
9	Rear Bumper	1	\$ 580.00	\$ 580.00
10	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
11	Rear Bumper Lower	1	\$ 280.00	\$ 280.00
12	Rear Bumper Under Cover	1	\$ 80.00	\$ 80.00
13	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
14	Rear Bumper Retainer LH	1	\$ 50.00	\$ 50.00
15	Rear Bumper Reflector RH	1	\$ 50.00	\$ 50.00
16	Rear Bumper Reflector LH	1	\$ 50.00	\$ 50.00
17	Rear Reinforcement	1	\$ 300.00	\$ 300.00
18	Rear Tail Lamp RH	1	\$ 400.00	\$ 400.00
19	Rear Tail Lamp LH	1	\$ 400.00	\$ 400.00
20	Rear Tail Lamp Clips	2	\$ 10.00	\$ 20.00
21	Rear Hyundai Emblem	1	\$ 60.00	\$ 60.00
22	Rear Elantra Emblem	1	\$ 60.00	\$ 60.00
23	Rear S Emblem	1	\$ 50.00	\$ 50.00
24	Rear Boot	1	\$ 1,580.00	\$ 1,580.00
25	Rear Boot Hinge RH	1	\$ 80.00	\$ 80.00
26	Rear Boot Hinge LH	1	\$ 80.00	\$ 80.00
27	Rear Boot Lower Latch	1	\$ 30.00	\$ 30.00
28	Rear Boot Lock	1	\$ 130.00	\$ 130.00
29	Rear Boot Rubber Seal	1	\$ 180.00	\$ 180.00
30	Rear Boot Lamp RH	1	\$ 280.00	\$ 280.00
31	Rear Boot Lamp LH	1	\$ 280.00	\$ 280.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2101-001

DATE : 4-Jan-2021

POLICY NO. : AVIVA

VEHICLE REG. NO. : SLS2057G

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Rear / End Panel Garnish	1	\$ 100.00	\$ 100.00
33	End Panel	1	\$ 380.00	\$ 380.00
34	End Panel Inner Bracket	1	\$ 80.00	\$ 80.00
35	Rear Spare Tyre Top Board	1	\$ 120.00	\$ 120.00
36	Rear Spare Tire Sink	1	\$ 380.00	\$ 380.00
37	Rear Exhaust Muffler	1	\$ 680.00	\$ 680.00
38	Rear Exhaust Rubber Bush	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 9,030.00
	<u>SPECIAL NETT</u>			
39	Front Number Plate with Frame	1	\$ 40.00	\$ 40.00
40	Rear Number Plate with Frame	1	\$ 40.00	\$ 40.00
41	Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
	<u>LABOUR</u>			
42	Spray Painting Whole Front and Whole Rear	1	\$ 1,800.00	\$ 1,800.00
43	Remove and Refit Front & Rear Affected Area	1	\$ 1,800.00	\$ 1,800.00
44	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
45	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
46	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
47	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 3,890.00
Amount Before Excess				\$ 13,200.00
Add GST @ 7%				924.00
Total Amount Payable				\$ 14,124.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.