

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST2101-001
DATE : 4-Jan-2021
POLICY NO. : AVIVA
VEHICLE REG. NO. : SL52057G
VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS ATTO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Bumper / CRU	1	\$ 580.00	\$ 580.00 474.40
2	Front Bumper Clip / NRC	10	\$ 5.00	\$ 50.00 30
3	Front Bumper Retainer RH X SVC	1	\$ 40.00	\$ 40.00 X
4	Front Bumper Retainer LH X SVC	1	\$ 40.00	\$ 40.00 X
5	Front Reinforcement ? X SVC	1	\$ 700.00	\$ 700.00 X
6	Front Sponge/absorber ? / CRU	1	\$ 180.00	\$ 180.00 ✓
7	Front License Garnish / SCR	1	\$ 40.00	\$ 40.00 ✓
8	Front Grille Assy / SCR	1	\$ 480.00	\$ 480.00 ✓
9	Rear Bumper / CRU	1	\$ 580.00	\$ 580.00 ✓
10	Rear Bumper Clips / NRC	10	\$ 5.00	\$ 50.00 30
11	Rear Bumper Lower / CRU	1	\$ 280.00	\$ 280.00 ✓
12	Rear Bumper Under Cover ? X SVC	1	\$ 80.00	\$ 80.00 X
13	Rear Bumper Retainer RH X SVC	1	\$ 50.00	\$ 50.00 X
14	Rear Bumper Retainer LH X SVC	1	\$ 50.00	\$ 50.00 X
15	Rear Bumper Reflector RH / CRA	1	\$ 50.00	\$ 50.00 ✓
16	Rear Bumper Reflector LH / CRA	1	\$ 50.00	\$ 50.00 ✓
17	Rear Reinforcement ? / BT.	1	\$ 300.00	\$ 300.00 ✓
18	Rear Tail Lamp RH X NN	1	\$ 400.00	\$ 400.00 X
19	Rear Tail Lamp LH / CRA	1	\$ 400.00	\$ 400.00 ✓
20	Rear Tail Lamp Clips / NRC	12	\$ 10.00	\$ 20.00 10
21	Rear Hyundai Emblem / NRC	1	\$ 60.00	\$ 60.00 ✓
22	Rear Elantra Emblem / NRC	1	\$ 60.00	\$ 60.00 ✓
23	Rear S Emblem / NRC	1	\$ 50.00	\$ 50.00 ✓
24	Rear Boot / DP	1	\$ 1,580.00	\$ 1,580.00 ✓
25	Rear Boot Hinge RH X R	1	\$ 80.00	\$ 80.00 X
26	Rear Boot Hinge LH X R	1	\$ 80.00	\$ 80.00 X
27	Rear Boot Lower Latch X SVC	1	\$ 30.00	\$ 30.00 X
28	Rear Boot Lock / Sum	1	\$ 130.00	\$ 130.00 ✓
29	Rear Boot Rubber Seal / CRU	1	\$ 180.00	\$ 180.00 ✓
30	Rear Boot Lamp RH ? X SVC	1	\$ 280.00	\$ 280.00 X
31	Rear Boot Lamp LH ? / CRA	1	\$ 280.00	\$ 280.00 ✓



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2101-001

DATE : 4-Jan-2021

POLICY NO. : AVIVA

VEHICLE REG. NO. : SLS2057G

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Rear / End Panel Garnish <i>CR4</i>	1	\$ 100.00	\$ 100.00
33	End Panel <i>pb</i>	1	\$ 380.00	\$ 380.00
34	End Panel Inner Bracket <i>X SVC</i>	1	\$ 80.00	\$ 80.00
35	Rear Spare Tyre Top Board <i>X SVC</i>	1	\$ 120.00	\$ 120.00
36	Rear Spare Tire Sink <i>X R</i>	1	\$ 380.00	\$ 380.00
37	Rear Exhaust Muffler <i>X SV</i>	1	\$ 680.00	\$ 680.00
38	Rear Exhaust Rubber Bush <i>X SVC</i>	2	\$ 30.00	\$ 60.00
Total Spare Parts				\$ 9,030.00
SPECIAL NETT				
39	Front Number Plate with Frame <i>pb</i>	1	\$ 40.00	\$ 40.00
40	Rear Number Plate with Frame <i>X SVC</i>	1	\$ 40.00	\$ 40.00
41	Reverse Sensor <i>Shox</i>	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 280.00
LABOUR				
42	Spray Painting Whole Front and Whole Rear	1	\$ 1,800.00	\$ 1,800.00
43	Remove and Refit Front & Rear Affected Area	1	\$ 1,800.00	\$ 1,800.00
44	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
45	Remove and Refit Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 80.00
46	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
47	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 3,890.00
Amount Before Excess				\$ 13,200.00
Add GST @ 7%				924.00
Total Amount Payable				\$ 14,124.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Repair day - 4 days
215

After paint photo

Sun Pin(LKK)

04/01/2020

TP within prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

**Supplementary
Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2101-001

DATE : 6-Jan-2021

POLICY NO. : AVIVA 10998919

VEHICLE REG. NO. : SLS2057G

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Antenna Device / CRA	1	\$ 70.00	\$ 70.00
Total Spare Parts				\$ 70.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
Total Labour				\$ -
Amount Before Excess				\$ 70.00
Add GST @ 7%				4.90
Total Amount Payable				\$ 74.90

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

4,579.52
56
240
1,900

6,755.52

p/p
\$6,775.52

7 days