

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21000109/KGA3Q2**Date:** 17/01/2022**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : SHF512M **Insured Vehicle No :** GBG8716E

Date of Loss: 27/12/2020 Nature of Claim: TP Claim No: MFL2020D0002868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF512M**
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001572
 Reg. Date: 13/06/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278248
 Colour: Metallic White/Red Odometer: 0 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Sailun 8 mm Rear Left Side: Firenza 8 mm
 Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
Approved Total (Overridden) (\$\$)		6,650.00		
(\$\$)	0.00	6,650.00	-6,650.00	
+ GST 7.00/7.00% (\$\$)	0.00	465.50	-465.50	
Nett Amount (\$\$)	0.00	7,115.50	-7,115.50	
+ Loss of Use (14.0 x S\$40.00/day) (\$\$)		560.00		
+ Car Rental (14.0 x S\$81.13/day) (\$\$)		1,135.82		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,818.77		
Global Sum Settlement (\$\$)		8,800.00		

INSPECTION

Date of Assignment: 04/01/2021

Date Inspected: 04/01/2021 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$25,201.00

LTA REIMBURSEMENT VALUE (RV) : \$18,573.00

NETT VALUE : \$6,628.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2021)
Parts:	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF512M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >