

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF512M

AAD2012-219

Not Notarized
T/loss

Vehicle No.:

Chassis No.:

04 JAN 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF512M

VF1ABL15AUC278248

RENAULT

LATITUDE

27/12/2020

III

13/06/2014

PART		LIST	
1	1 BUMPER COVER REAR	\$	B ₁ 561.70 ✓
2	1 BUMPER LOWER REAR	\$	B ₁ 411.90 ✓
3	1 BUMPER REFLECTOR LH	\$	B _{no} 16.60 ✓
4	1 BUMPER BRACKET CTR REAR	\$	CM 98.10 ✓
5	1 BUMPER BRACKET SIDE RH REAR	\$	CM 82.10 ✓
6	1 BUMPER RETAINER RH REAR	\$	DI 59.80 ✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	DI 80.80 ✓
8	1 BUMPER RETAINER LH REAR	\$	CM 54.20 ✓
9	1 ABSORBER REAR	\$	NJP 217.30 X
10	1 BUMPER BEAM REAR	\$	B ₁ 547.80 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	B ₁ 114.50 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	B ₁ 114.50 ✓
13	1 OUTER PANEL REAR (End Panel)	\$	B ₁ 745.80 ✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM 404.56 ✓
15	1 SPARE WHEEL PANEL	\$	B ₁ 1,229.40 ✓
16	1 SPARE WHEEL PANEL BRACKET LH	\$	B ₁ 70.60 ✓
17	1 SPARE WHEEL PANEL BRACKET RH	\$	B ₁ 69.20 ✓
18	1 FENDER PANEL FRT RH	\$	B ₁ 437.10 ✓
19	1 FENDER PANEL FRT LH	\$	B ₁ 437.10 ✓
20	1 FENDER PANEL INNER REAR LH	\$	R 1,241.60 X-
21	1 FENDER PANEL INNER REAR RH	\$	R 1,241.60 X
22	1 SPARE TYRE BOARD	\$	CM 680.90 ✓
23	1 FENDER INNER BOARD LH	\$	Return 561.40 ✓
24	1 FENDER INNER BOARD RH	\$	L 561.40 ✓
25	1 WHEEL HOUSE PRE ASSY LH (CENTER)	\$	R 1,241.60 X
26	1 WHEEL HOUSE PRE ASSY RH (CENTER)	\$	B ₁ 1,241.60 ✓
27	1 SILL PANEL OUTER LH	\$	R 1,902.00 X
28	1 SILL PANEL INNER LH	\$	R 483.20 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2012-219

SHF512M

29	1 SILL PANEL OUTER RH
30	1 SILL PANEL INNER RH
31	1 TAILLAMP LH
32	1 TAILLAMP RH
33	1 EXHAUST CAP REAR
34	1 BOOT REAR
35	1 BOOT BADGE 'RENAULT'
36	1 BOOT BADGE
37	1 BOOT REFLECTOR LAMP LH
38	1 BOOT REFLECTOR LAMP RH
39	1 BUMPER REFLECTOR LH
40	1 BUMPER REFLECTOR RH
41	1 BOOT HINGE LH
42	1 BOOT HINGE RH
43	1 BOOT STRUT LH
44	1 BOOT STRUT RH
45	1 BOOT LOCK LINKAGE
46	1 BOOT LOCK LINKAGE HOLDER
47	1 BOOT LOCK
48	1 BOOT LOCK CATCH
49	1 BOOT FINISHER
50	1 BUMPER COVER FRT
51	1 BUMPER SPOILER FRT
52	1 BUMPER ABSORBER FRT
53	1 BUMPER RETAINER FRT LH
54	1 BUMPER SUPPORT FRT
55	1 BUMPER RETAINER FRT RH
56	1 BUMPER SUPPORT FRT
57	1 BUMPER UNDERTRAY FRT
58	1 BUMPER GRILLE LOWER FRT
59	1 BUMPER FOG LAMP GRILLE LH
60	1 BUMPER FOG LAMP GRILLE RH
61	1 BUMPER BEAM FRT
62	2 BUMPER BEAM PAD FRT
63	1 TOW COVER FRT
64	1 RADIATOR GRILLE
65	1 RADIATOR GRILLE BADGE 'RENAULT'
66	1 RADIATOR GRILLE FRAME

\$	Bu	1,856.50	✓
\$	n	371.10	✓
\$	m/c M	401.40	—
\$	Bro	401.40	—
\$	R1	125.40	✓
\$	R1	1,677.20	—
\$	m	82.40	—
\$	m	95.80	—
\$	CM	277.70	—
\$	Bro	277.70	✓
\$	CM	16.60	✓
\$	Bro	16.60	✓
\$	B	254.20	✓
\$	B	254.20	✓
\$	Tn	145.10	—
\$	Tan	145.10	—
\$	Sn	20.60	X
\$	Sn	99.50	X
\$	R1	246.60	✓
\$	R1	41.70	✓
\$	CM	344.70	—
\$	Bro/CM	747.20	✓
\$	Sn	344.70	X
\$			
\$	CM	101.40	—
\$	D11	10.70	—
\$	CM	101.40	—
\$	D11	10.70	✓
\$	Sn	292.50	X
\$	CM	147.00	✓
\$	Sn	207.21	X
\$	m11	207.21	✓
\$	R1	663.70	✓
\$	Sn	24.50	X
\$	Sn	60.90	X
\$	CM	969.90	✓
\$	m	225.36	✓
\$	CM	686.00	✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2012-219**SHF512M**

67	1	FRAME FULL SUPPORT PANEL	\$	CM	592.70	✓
68	1	FRAME FULL SUPPORT BRACKET	\$	Dir	41.60	—
69	1	FRONT BRACE PANEL	\$	Dir	177.22	—
70	1	HORN	\$	SC	449.90	X
71	1	HORN BRACKET	\$	SC	21.90	X
72	1	HEADLAMP LH	\$	CM	743.60	—
73	1	HEADLAMP RH	\$	my CM	743.60	—
74	1	HEADLAMP PANEL FRT LH	\$	Bu	127.70	—
75	1	HEADLAMP PANEL FRT RH	\$	Bu	128.30	—
76	1	HEADLAMP HARNESS	\$	SC	556.10	X
77	2	HEADLAMP ADJUST MOTOR	\$	SC	313.90	X
78	1	BONNET	\$	Bu	1,312.70	✓
79	1	BONNET INSULATOR	\$	SC	294.30	X
80	1	BONNET STRUT LH	\$	SC	53.30	X
81	1	BONNET STRUT RH	\$	SC	53.30	X
82	1	BONNET HINGE LH	\$	Dir	236.50	—
83	1	BONNET HINGE RH	\$	Dir	237.40	—
84	1	BONNET LOCK	\$	Tu	152.80	✓
85	1	BONNET CABLE	\$	SC	55.20	X
86	1	BONNET CABLE COVER	\$	SC	80.60	X
87	1	BONNET SEAL OUTER	\$	SC	83.20	—
88	1	BONNET SEAL INNER	\$	SC	70.10	X
89	2	BONNET BUFFER	\$	SC	26.80	X
90	1	FENDER PANEL FRT LH	\$	Bu	414.40	✓
91	1	WHEELARCH FRT LH	\$	SC	112.30	X
92	1	FENDER BRACKET LOWER LH	\$	SC	11.80	X
93	1	FENDER INSULATOR LH	\$	SC	65.50	X
94	1	FENDER BRACKET FRT LH	\$	X	38.90	X
95	1	FENDER PANEL FRT RH	\$	Bu	414.40	✓
96	1	WHEELARCH FRT RH	\$	Dir	191.40	✓
97	1	FENDER BRACKET LOWER RH	\$	SC	21.40	X
98	1	FENDER INSULATOR RH	\$	SC	66.30	X
99	1	FENDER BRACKET FRT RH	\$	X	106.40	X
100	1	WIPER RESERVOIR	\$		179.60	X
101	1	WIPER RESERVOIR NECK	\$		29.30	X
102	1	WIPER RESERVOIR MOTOR	\$		82.60	X
103	1	AIR CLEANER LOWER	\$		271.26	X
104	1	AIR CLEANER HOSE	\$		76.14	X

Trans-cab Auto Services Pte Ltd ***AAD2012-219**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF512M

105	1	BASE BATTERY TRAY	\$	363.40	X
106	1	AIR CLEANER BOX	\$	464.20	X
107	1	TURBO DUCT	\$	1,027.80	X
108	1	A/C HEATER VALVE	\$	484.50	X
109	1	SUBFRAME OUTER FRT	\$	1,094.20	X
110	1	SUBFRAME BRACKET OUTER LH	\$	49.00	X
111	1	SUBFRAME BRACKET OUTER RH	\$	49.00	X
112	1	ENGINE UNDERTRAY	\$	583.10	X
113	1	A/C CONDENSER	\$	1,537.80	✓
114	1	A/C CONDENSER GARNISH LH UPPER	\$	57.30	—
115	1	A/C CONDENSER GARNISH RH UPPER	\$	56.70	—
116	1	A/C CONDENSER GARNISH LH	\$	67.90	X
117	1	A/C CONDENSER GARNISH RH	\$	67.70	X
118	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	187.20	X
119	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	380.20	X
120	1	A/C PIPE COMPRESSOR	\$	222.70	X
121	1	A/C PIPE	\$	486.50	X
122	1	A/C COMPRESSOR	\$	2,142.30	X
123	1	AIR COOLER	\$	598.90	X
124	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	X
125	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	X
126	1	TRANSMISSION COOLER	\$	1,219.30	X
127	1	TRANSMISSION COOLER PAD	\$	9.50	X
128	1	RADIATOR	\$	871.20	X
129	2	RADIATOR STUD UPPER	\$	11.10	X
130	2	RADIATOR BUSH UPPER	\$	11.10	X
131	2	RADIATOR MTG LOWER	\$	30.10	X
132	1	RADIATOR FAN COWLING	\$	417.00	✓
133	1	RADIATOR FAN MOTOR LH	\$	826.70	X
134	1	RADIATOR FAN MOTOR RH	\$	821.20	X
135	1	RADIATOR TANK	\$	174.80	X
136	1	RADIATOR HOSE UPPER	\$	97.50	X
137	1	RADIATOR HOSE LOWER	\$	254.10	X
138	1	RADIATOR TANK HOSE	\$	56.20	X
139	1	AUTO COMPUTER	\$	1,287.30	X
140	1	INJECTION COMPUTER	\$	2,706.30	X
141	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	3,765.30	X
142	1	STEERING PUMP ELECTRIC L70Y	\$	2,026.70	X

Trans-cab Auto Services Pte Ltd

AAD2012-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF512M

143	1	STEERING PINION RACK L70Y	\$	Sm	3,765.30	X
144	1	STEERING HOSE LOW PRESSURE LONG	\$	Sm	397.40	X
145	1	STEERING HOSE LOW PRESSURE	\$	Sm	221.90	X
146	1	FUSE BOX	\$	Sm	987.39	X
147	1	ENGINE MOUNTING RH	\$		153.50	X
148	1	ENGINE MOUNTING LOWER	\$		149.20	X
149	1	ENGINE MOUNTING UPPER	\$		592.02	X
150	1	ENGINE HARNESS L70Y	\$	N	1,501.60	X
151	1	SUPPORT ENGINE UPPER	\$	Sm	610.37	X
152	1	ALTERNATOR	\$		1,442.30	X
153	1	BATTERY	\$	Sm	350.00	X
154	1	BATTERY COVER	\$		363.40	X
155	1	LOWER ARM LH L70Y	\$	Sm	192.70	X
156	1	KNUCKLE ARM LH L70Y	\$	Sm	481.50	
157	1	ABSORBER FRT LH L70Y	\$	Sm	274.10	
158	1	DRIVESHAFT LH	\$	N	1,355.70	
159	1	STABILIZER BAR FRT	\$	Sm	427.90	
160	2	STABILIZER LINK FRT	\$	Sm	69.50	
161	1	LOWER ARM RH L70Y	\$	Sm	192.70	
162	1	KNUCKLE ARM RH L70Y	\$	Sm	481.50	
163	1	ABSORBER FRT RH L70Y	\$	Sm	274.10	
164	1	DRIVESHAFT RH	\$	N	1,355.70	
165	1	KNUCKLE ARM SHIELD LH	\$	Sm	96.20	
166	1	KNUCKLE ARM PLATE LH	\$	Sm	120.80	
167	1	KNUCKLE ARM SHIELD RH	\$	Sm	96.20	
168	1	KNUCKLE ARM PLATE RH	\$	Sm	120.80	
169	1	KNUCKLE HUB+BEARING LH	\$	na	272.30	
170	1	KNUCKLE HUB+BEARING RH	\$	na	272.30	
171	1	ABSORBER MOUNTING KIT LH	\$	Sm	212.30	
172	1	ABSORBER DUST COVER LH	\$	Sm	76.30	
173	1	ABSORBER MOUNTING KIT RH	\$	Sm	212.30	
174	1	ABSORBER DUST COVER RH	\$	Sm	76.30	
175	1	BRAKE DISC FRT LH	\$	Sm	158.80	
176	1	BRAKE DISC FRT RH	\$	Sm	158.80	
177	1	SUBFRAME INNER FRT	\$	Sm	746.00	
178	1	SUBFRAME SUPPORT INNER	\$	Sm	69.50	
179	1	SUBFRAME BRACKET INNER FRT LH	\$	N	101.00	
180	1	SUBFRAME BRACKET INNER FRT RH	\$	N	101.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2012-219

SHF512M

181 1 ENGINE TOP COVER 2.0

\$	<i>Per</i> 139.80 X
\$	80,060.21
10% \$	8,006.02
\$	72,054.19

Specical Nett

1 1SET PARKING AID	\$	<i>Shot</i> 700.00 <i>400SN</i>
2 1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
3 1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 X
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
5 1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
7 1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
8 1SET BONNET LOCK NUT	\$	<i>na</i> 60.00 X
9 1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
10 1 EXHAUST MOUNTING REAR	\$	<i>Dis</i> 17.82 ✓
11 1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i> 80.00 <i>30SN</i>
12 1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>30SN</i>
13 1 BUMPER CLIP FRT	\$	<i>na</i> 85.00 <i>66SN</i>
14 1 BUMPER RETAINER CLIP FRT	\$	<i>na</i> 70.00 X
15 1 BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 70.00 X
16 1 BUMPER FOG LAMP GRILLE CLIP	\$	<i>na</i> 65.00 X
17 1 LICENSE PLATE WITH HOLDER FRT	\$	<i>By</i> 120.00 <i>45SN</i>
18 1 BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i> 10.50 X
19 1SET RADIATOR GRILLE SCREW	\$	<i>na</i> 16.00 ✓
20 1SET BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00
21 1SET FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00
22 2 FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00
23 2 FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00
24 1 Windscreen moulding	\$	<i>na</i> 120.00
25 1 FRONT WINDSCREEN SEALANT	\$	<i>na</i> 109.20
26 1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00
27 6 BONNET INSULATOR CLIP L70Y	\$	<i>na</i> 7.30
28 2 BONNET CABLE CLIP L70Y	\$	<i>na</i> 6.31
29 2 BONNET CABLE COVER SCREW L70Y	\$	<i>na</i> 10.85
TOTAL	\$	2,141.99
TOTAL PARTS	\$	74,196.18

Trans-cab Auto Services Pte Ltd*

AAD2012-219

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF512M

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	28601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	✓
To Rust-Proofing Of The Affected Areas.	\$	170.00	1501
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} 1001
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	1001
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
To Check Electrical Lighting Concerned.	\$	170.00	401

TOTAL \$ 7,580.00**Over All Total \$ 153,830.37**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF512M**AAD2012-219****(LUMP SUM)****Repair Days****30 DAYS****24 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: