

# YAP MOTOR REPAIR SERVICE

Blk 7 #01-82 Sin Ming Road Singapore 575642


Tel: 6451 1705 Fax: 6451 1706 H/P: 9618 7155 / 8161 9189

Roc: 10739200C Email: yapmotorrepair@singnet.com.sg

Quotation

VEHICLE NO: <b>ER 828A</b>				MODEL / CHASSIS			
				MILEAGE: _____ KM			
OWNER				CONTACT:	HP	<b>To 87a</b>	
					TEL		
DATE	IN	TIME	IN	FUEL:	1/4	1/2	3/4
	OUT		OUT				
	<b>26/12</b>		<b>11:00am</b>				

Comments / Remarks:	Amount
1. Knock ✓	
2. \$260	
3.	
4. Spraypainting ✓	
5.	
6.	
7. <del>Parts</del>	
8.	
9.	
10.	
11.	
12.	
13.	
14.	
15.	
16. <del>Wheel Alignment</del>	
17. <del>Air Con Gas</del>	
18. <del>Towing</del>	
19. Total Amount	<b>\$280</b>



P/P \$260 1day

Note :

1. Kindly remove your cashcard & valuables from vehicle. The Management shall not be liable for loss of cash, valuable items or any articles of importance from the vehicle.
2. We accept the following modes of payment: cash, Nets, Visa & Mastercard.
3. Additional service operations may be required for your vehicle make/model and will charged at extra cost. Some parts sold are for highway use only and not street vehicles.

Registered Owner Vehicle Signature : \_\_\_\_\_

Date : \_\_\_\_\_

Total Amount : \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_