



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104747

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 06/07/2021
Reference CC6/CTI21000129/T1ra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 4929M
Insured Veh. GBK 3350M
Claim No. SNM20D204992
Policy No. DMCVSNW00036162000
Accident Date 22/12/2020
Inspection Date 29/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21000129/T1ra3q2 Date: 06/07/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 3350M	Veh. Inspected	GBK 4929M
	Policy No.	DMCVSNW00036162000	Coverage (\$)	0.00
	Claim No.	SNM20D204992	Excess (\$)	0.00
	Assign From		Assign Date	29/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTFAT35Y00K215188	Colour	SILVER
	Odometer	9039 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	195/75 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm
	L/H Rear Tyre	155 R12 (D)	BRIDGESTONE	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/12/2020	Inspection Date	29/12/2020
	Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 4929M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAIL GATE	BENT	1,514.00	1,365.00
1	TAIL GATE STICKER (DYNA)	NECESSARY	102.00	102.00
1	TAIL GATE STICKER (TOYOTA)	NECESSARY	217.50	174.10
2	TAIL GATE SIDE HANDLE @\$179.00	TO REPAIR SEE LABOUR	358.00	-
2	TAIL GATE SIDE LOCK @\$215.00	BENT	430.00	342.00
2	TAIL GATE SIDE LOCK BRACKET @\$276.30	BENT	552.60	552.60
2	TAIL GATE LOWER SIDE RAILING @\$246.90	BENT	493.80	493.80
4	TAIL GATE LOWER SIDE RAILING MOUNTING @\$25.00	NOT NECESSARY	100.00	-
4	TAIL GATE HINGE @\$124.10	BENT	496.40	385.60
2	REAR SIDE GATE @\$1879.50	N/S TO REPAIR SEE LABOUR / O/S DENTED	3,759.00	1,879.50
1	END PANEL	BENT	564.20	564.20
1	REAR FLOOR PANEL	NOT NECESSARY	1,854.00	-
2	TAIL LAMP @\$354.90	CRACKED	709.80	570.60
2	TAIL LAMP BRACKET @\$172.40	BENT	344.80	344.80
1	REAR CAR PLATE BRACKET	BENT	186.00	186.00
2	REAR CAR PLATE LAMP @\$60.00	MISSING	120.00	120.00
1	SPARE TYRE HOLDER	TO REPAIR SEE LABOUR	350.00	-
1	REAR EXHAUST PIPE	BENT	467.00	467.00
1	REAR EXHAUST TOP MOULDING	NOT NECESSARY	30.00	-
1	REAR EXHAUST TOP MOULDING BRACKET	NOT NECESSARY	67.30	-
	LESS 25% DISCOUNT		-3,179.10	-1,886.80
			9,537.30	5,660.40
<u>SPECIAL NETT ITEMS</u>				
1	TAIL GATE ALUMINIUM PLATE (SN)	BENT	1,200.00	400.00
1	TAIL GATE ALUMINIUM PLATE RIVET (SN)	NECESSARY	120.00	60.00
1	TAIL GATE STICKER (70KM/H) (SN)	NECESSARY	40.00	40.00
2	SIDE GATE ALUMINIUM PLATE @\$1000.00(SN)	NOT NECESSARY	2,000.00	-
1	SIDE GATE ALUMINIUM PLATE RIVET (SN)	NECESSARY	100.00	60.00

Report Ref No. CC6/CTI21000129/T1ra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SIDE GATE COMPANY STICKER (SN)	NECESSARY	600.00	400.00
1	FLOOR PANEL ALUMINIUM PLATE (SN)	BENT	1,600.00	600.00
1	FLOOR PANEL ALUMINIUM PLATE RIVET (SN)	NECESSARY	100.00	60.00
1	REAR CAR PLATE (SN)	CUT	60.00	40.00
1	REVERSE SENSOR (LONG) (SN)	NECESSARY	550.00	200.00
2	REVERSE SENSOR HOLDER @\$20.00(SN)	NOT NECESSARY	40.00	-
1	END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	FLOOR PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR STEP PANEL (SN)	NOT NECESSARY	400.00	-
			6,970.00	1,900.00
	LABOUR			
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAIL GATE SIDE HANDLE , REAR SIDE GATE LH AND SPARE TYRE HOLDER .		1,500.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	800.00
	TO PERFORM LIGHTING & WIRING CHECK .		100.00	30.00
	TO APPLY ANTI-RUST & TUFF-KOTE.		200.00	40.00
	REMOVE AND INSTALL REAR EXHAUST .	NOT NECESSARY	300.00	-
	REMOVE AND INSTALL TAIL GATE ,SIDE GATE .		360.00	100.00
	REMOVE AND RESEAL GATE RIVET SET .		300.00	100.00
	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS.		100.00	30.00
	REMOVE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS .		150.00	60.00
			4,410.00	1,960.00
GRAND TOTAL			20,917.30	9,520.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,600.00

Report Ref No. CC6/CTI21000129/T1ra3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 4929M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 4929M

RE-INSPECTION

