ASS. REC. BY:	
Kenneth	SIGNMENT
Emm.	
Estimated Cost: Date:	Veh No: SLD 2093 Eyr Regn: 06, 16  Type: M.Carl M.Cycle / Bus / Van / Lore / Tank / Bus / Van / Lore / Bus / Van / Lore / Bus / Van / Lore / Tank / Bus / Van / Lore / Bus
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Type: M.Car/ M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
Al Wortehan mile	Make: Mit lance EX c.c 1590
of Chen Hoe	Colour M. Re AC: Insured / Std / NI / NA
Insured:	Sp.Reading 131438 T/Radio: Insured / Std / NI / NA
Policy No.	_   Eng/No:
Claims No.	Gen Cond: CARSING SECYLAG. U 004550
Sum Insured: Excess: 1300/	John Good Frair / Poor / Burnt
(Client's Record)	Steering: Inorder/ Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: NII / S/Rim / STD A/Rim or
(Policy Condition)	Tyre Stze: F: 205/60R16
Remark: The veh had commenced its N/S O/S	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Bal. or Market Value: 8 44K	тоуо угоко ог
IDAC Accident Rport: Consistent?: Yes or No	Rear 7
GIA / PR Seen: Consistent?: Yes or No	I/Rai 7 mm R/Bai mm
Est. Repairs: Off days Res.: Yes or No	DOA 21/12/2
Lum Sum: 1.B.1 % 3 Val.: Yes or No	Survey held at D.O.I. 5 / 1 / 2021
CA / REY / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	By W/s Wis Tole I Rooftop or
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Account insudction	The Common of th
Oate/Time, File Pass to? Prell. Report Da	ys Of Repair:
A. C.	
Outa/Time, File Return to?	Survey No. of Trip:    Survey Fee:
Z) Add Fee:	: Site Insp (\$ )s - Rssi
· ^	: Interview (\$ ) Fires
Report Format :	Tech Invs (\$ ) Others
Lump Sum / I.B.I: (S	Weekend (\$
	TOTAL

Cheng Hoe Motor Pte Ltd #01-374/382,Blk 1019, Yishun Industrial Park A 768761

Insurer Reference: SLD2093E Repairer Reference: A0167

Date calculated: 04/01/2021 5:23 PM

SLD 2093E OD/china

Full Report Registration: SLD2093E Printed: 04/01/2021 5:37 PM

**Summary Information** 

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance (Singapore) Pte Ltd

Printed by:

Claim Reference: Estimated Repair Time: Actual Repair Days: CHENG HOE SLD2093E

Currency:
Date of Incident:
Hire Car Start:
Hire Car End:

SGD 21/12/20

**Vehicle Details** 

**Vehicle** 

Manufacturer:

MITSUBISHI

Model:

LANCER (CY,CX,CZ)

Sub Model:

EX 32 39 57

Model Sheet Number: Registration:

SLD2093E

VIN number:

JMYSRCY1AGU004550

Odometer:

Model Specs

FROM 03/2016

AIR CONDITIONING

FOG LAMPS

1.6 LTR 85/86/91KW

Not Norhanks Rinny Ble pain

4-DOOR SALOON TWO COAT METALLIC

PREPARE OFF VEHICLE

**Vehicle Condition** 


**Vehicle Status** 

Pre-Accident Damage: Date of Inspection:

**Damage Areas** 

All

Underbody



bour	Time Base 10	WU/h	Drid	20 - 42 0	0.000 //
Code	Description	110/11	РПС	e = 42.0 WU	0 SGD/h Price SGD
					. Hee Sap
NO NUMBER	PREPARATION TIME			2.0	8.40
14110 00	R + R FRONT BUMPER			8.0	33.60
NO NUMBER	RENEW FRONT BUMPER (REMOVED)			12.0	50.40
	INCLUDES: R + R FOG LAMPS AND NECE	SSARY		12	
IO NUMBER	ATTACHED PARTS		到的情報	Latercas	17-16-6
IO NOMBER	R + R FRONT BUMPER REINFORCEMENT			3.0	12.60
22022 10)	(BUMPER REMOVED) R + R L/F WING		THE CONTRACTOR	and the same of th	
22022 10)	INCLUDES: R + R HEADLAMP AND WHEE	LADCU		9.0	37.80
	TRIM	LAKCH			
O NUMBER	ADJUST HEADLAMPS				A EXHIBITED
019	L/F PANEL REPAIR	NEWS STATES OF THE STATE OF THE	and the same of th	2.0 10.0*	8.40
167	L/F UP W-HOUSE REINF REPAIR				42.00
	4. S. W HOOSE KEINF REPAIR			10.0*	42.00
	Labour Cost		Hrs	WU	
	Panel / Mechanical Labour		5.60	56.0	235.20
			5.00	30.0	233.20
	Total of Labour				235.20
Paint					
Paint Work	SYSTEM	AZT	Tir	ne Basis	10 WU/h
Code	Description - TWO COAT METALLIC	-			
couc	Description - TWO COAT METALLIC			WU	Price SGD
	FRT BUMPER REINF SURFACE PAINT			4.0	
aitz	L/F WING NEW PART PAINTING			10.0	
A CKOO DOO	FRONT BUMPER COVER NEW PART PAINT	K1R	W. OTE10	13.0	
FORM FAT	L/F PANEL SURFACE PAINT		Contact And Spring	4.0	
	L/F UP W-HOUSE REINF SURFACE PAINT			4.0	
	LEFT FRONT DOOR SURFACE PAINT	and the second s	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IN COLUMN TO THE PERSON NAMED IN COLUM	8.0	Madikan wa 2 mit ya 2
Paint Mater	ial Per Part				
Code	Description				Price SGI
0340	FRT BUMPER REINF SURFACE PAINT		anti-dental		2.4
0741	L/F WING NEW PART PAINTING				and the control of the same of the same
0283	FRONT BUMPER COVER NEW PART PAINT	ΓK1R	ATTENNA OF	0.5.12.95.55	21.1 64.9
1019	L/F PANEL SURFACE PAINT	and the second of the second o			0.5
1167	L/F UP W-HOUSE REINF SURFACE PAINT	- English Name of Land	6/03/6/6/5	29/27/24/23/200	1.4
1481	LEFT FRONT DOOR SURFACE PAINT				22.1
					21000
	Labour Cost - Paint		Urs	14/11	Duice CC
	Factor	42.00 SGD/h	Hrs	WU	Price SG
	Time Paint	72.00 300/11		42.0	
	Preparation Main Work Metal		3 50	43.0	
	Preparation Comp. Work Plastic		2.50		
	Total	10 WU/h	0.50 7.30		21.0
		10 100/11	7.30	73.0	306.6

Audatex System Using Manufacturer Times

Page 2 of 4

PRINT DATE 04/01/2021

Material Cost - Paint	Price SGD
New Part Painting	21.16
New Part Painting - Plastic K1R	64.94
Surface-/Blend Paint	26.64
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	150.34

**Spare Parts** 

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER COVER	6400H438	Original	CM 390.00 -
0340	FRT BUMPER REINF	6400A832	Original	190.00 7
0410	GRILLE	7450A780	Original	CM 290.00 -
0355	L/F BUMPER BRACKET	6400F549	Original	011 18.00 -
0637	L/F FOG LAMP CPL	8321A663	Original	210.00 7
0741	L/F WING	5220G043	Original	ے 210.00 س
0575	LEFT HEADLAMP ASSY	8301C373	Original	CM 410.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Fixed Sundry Parts	Price		0.00 1,718.00 100.00
	Total			1,818.00

#### **Final Calculation**

Tillal Calculation		
	SGD	SGD
Parts	1,718.00	
Fixed Sundry Parts Price	100.00	
Total Parts		1,818.00
Labour Time Base 10 WU/h		
Total 56.0 WU X 42.00 SGD/h	235,20	
Total of Labour		235.20
Paint Work Time Base 10 WU/h		
Labour Cost 73.0 WU X 42.00 SGD/h	306.60	
Material Cost	150.34	
Total Paint Including Material		456.94
Repair Cost Excludes GST		2,510.14
GST (+7.0%)		175.71
Repair Cost Included GST		2,685.85

#### **Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

## **Assessment Note**

Audatex System Using Manufacturer Times

Page 3 of 4

PRINT DATE 04/01/2021

# to One Motoring

ire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Company
Owner ID:	322N
Vehicle Details	
Vehicle No.:	SLD2093E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Jan 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	4A92CH8182
Chassis No.:	JMYSRCY1AGU004550
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$13,955.00
Original Registration Date:	08 Jun 2016
First Registration Date:	08 Jun 2016
Transfer Count:	2
Actual ARF Paid:	\$13,955.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jun 2026
PARF Rebate Amount:	\$10,466.00
Intended COE Rebate Details	27.1 2007
COE Expiry Date:	07 Jun 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,700.00
COE Rebate Amount:	\$25,495.00
Total Rebate Amount:	\$35,961.00

The information contained herein is correct as at 05 Jan 2021

OK

## SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

In Please report correctly the details of the accident to speed up the claims process.

1. Please report must be completed by the Policyholder and/or the Authorised Driver
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission ..... 22/12/2020 17:02 (SGT) Date of Accident 21/12/2020 16:30 (SGT) Exact Location of Accident Singapore Additional Location Information **SUN PLAZA** Country/State of Loss ..... Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLD2093E

#### INSURED/POLICYHOLDER

LINK 2 LINK ASIA PACIFIC PTE LTD Name Of Registered Owner 2XXXXX322N Company Reg No ..... Email Address ..... hootai.chua@link2linkco.com (Phone) +65-62622216 Mobile Phone No ..... (Office) +65-62622216 Alternative Phone No .....

Mitsubishi Lancer Model ..... Variant ..... Exact purpose for which vehicle was being used at time of **Employment** accident ..... Are you claiming under your own insurance policy for repair to Yes your vehicle? ..... Private car Vehicle Category .....

Name of Insurance Company China Taiping Insurance Type of Coverage ...... Comprehensive Fleet Policy No Policy Number ..... DMPCSNW00169792000 Cover Note Number 08/12/2020 - 07/12/2021

### DRIVER

Name of Driver TAN CHIA HUAT (CHEN ZHENGFA) NRIC No SXXXX924D Date Of Birth 24/11/1971 Occupation Outdoor

Accident report SC0920CM0003

Page 1 of 13

也是我是我人的大概就!

. His project a continue of contractions of the service of self-

a panedarion accompanie of the manufact

	25/10/1995	and care transport
	25/10/1995 25 YEARS AND 2 MONTHS	S
Date Of Driving Pass		The last many
Driving experience	Male (Phone) +65-92726598	3 .7
Gender		17
Mobile Number	tanchalone@hotmail.com	107 112
Alt. Phone Number	tanchalone@hotmail.com BLK 507A YISHUN AVE 4 #	10/-112
Email Address	BLK 3077	The state of the s
Address	-04507	W.
Address complement	761507	THE TAKE THE PARTY OF
Address complement Postcode	No	
Postcode Is the driver the policyholder?	Employee	
If No, Relationship of the Diver Was as	No	
Does Driver Own Other Vehicle Owned by Driver	• ed to 86 th a harriest to the time	
Insurance Company of Other Vehicle Owned by Driver	- Administrative	
Insurance Company of Other Vehicle Office Office	and the latest the selection of	AND AS A CONTRACT OF THE PARTY
Street Control of the	Andrews A. S.	and the second s
GENERAL INFORMATION OF THE ACCIDENT		
	Collision - Head to Rear	
Type of Accident	Clear	
Weather Conditions	Dry	
Road Surface	٥٠,	(1975年)。村市首代21年(1976年)
Charles and the second		abserta out all material processors
OTHER INFORMATION		man and a grant heath and h
a section.		
Was any foreign vehicle involved in the accident?	No	
Number of vehicles involved in the accident	2	
Was anybody injured in the Accident?	No	
Was any injured conveyed to hospital by ambulance?	- Yes	
Was any other material or property damaged?	1	
Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s)		
soliciting/offering accident claims assistance?	No	
Constant of the second of the	er a service of the control of the c	
DETAILS OF POLICE ACTION		were to be presented and
Tardina of the same and a second of	Q 010 177, 400 000 000 000 000 000 000 000 000 00	
Was the accident reported to the police?	No	
Was notice of intended Prosecution given?	No	
If yes, against whom?		
1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	social providence and the second	
CIRCUMSTANCES OF ACCIDENT		
\$17 is 1981		
REFER TO STATEMENT	attra con .	A STATE OF THE STA
ATTACHMENT(S)		market and the state of the state of
Are accident photos available for attachment?		
Man thoro any video cantured by Car Camera?	Yes	
Was there any audio recorded?	No	
	R VEHICLE PROPERTY 1	
DETAILS OF OTHER	VEHICLE FILE	
- I wis Number	SFX2724A	
Vehicle Registration NumberVehicle Manufacturer	•	
Vehicle Manufacturer Vehicle Model	-14	
Vehicle Variant	•0 Care	
Vehicle Colour	-	
Vehicle Category	Private car	
Name of Driver	HAFEEZ	
Contact Number	•	
Addross		France (1, 20)
Address complement	-	
Postcode	•	
Insurance Company Name	•	
ga sad.		Page 2 of 13
mp		Page 2 01 13
Accident report SC0920CM0003		

11	ASS. REC. BY:
re	nnerh A. JID DOO27
	Estimate the state of the state
	09//
1	
1	
-1	74612
- '	Cocation -
Ī	Sup Play n
r	DESCRIBE CIRCUMSTANCES OF THE ACCIDENT
-	VENICLE NO. OLD 2043E ((MINA)
	Date & Time: 91/15/2050 (N 1630 (May an)
١	in the restriction of the state
	As I was approaching the exit of Jun Plaza (upslepe), I saw
	Motor car SKX 2724A sort of reversing to give way to pedestrion
	As such my vehicle front portion had collided onto the mar of
	SKX 272 VA. No me was injured
	the same of the sa
	. And it comested for an employed as a making as in the flow graph and in the comment of
b. 1	SET OF STONE OF CONTROL AND
	the tradest while his new letters where he had before the property to be accounted to the property of the property of
	and the second s
	The state of the court of the same of the population and the property of the same of the court of the same of the court of
	The speciments of the first own is an expensive and the second of the se
	The second of the complete party of the property of the proper
	The first exemple of the particle and the first the Harrist who is not a first the first
	the first of the second of the
	Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim
	under your own comprehensive policy. Please check with your policy for more unormalism.
	DECLARATION  We declare the foregoing particulars are true in every respect.
	Construction of the state of th
	Policyholder's Signature  Driver's Signature  (If driver is not the policyholder)  NRIC/FIN No.: