

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21000130/KTD3Q2**Date:** 01/02/2021**REFERENCE**

Insured/Claimant: LINK2LINK ASIA
PACIFIC PTE LTD Policy No: DMPCSNW00169792000

Date of Loss: 21/12/2020 Nature of Claim: OD Claim No: SNM20D204988/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD2093E**

Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4A92CH8182

Reg. Date: 08/06/2016 (Man. Year: 2016) Chassis No: JMYSRCY1AGU004550

Colour: Metallic Red Odometer: 131438 km

Engine Capacity: 1590 cc

Market Value/New Car Price: S\$44,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,718.00	1,400.00	318.00	18.51
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	692.14	671.14	21.00	3.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,510.14	2,171.14	339.00	13.51
- Excess (S\$)	0.00	1,300.00	-1,300.00	
(S\$)	2,510.14	871.14	1,639.00	65.30
+ GST 7.00/7.00% (S\$)	175.71	60.98	114.73	65.30
Nett Amount (S\$)	2,685.85	932.12	1,753.73	65.30

INSPECTION

Date of Assignment: 05/01/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 05/01/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jan 2021)
Parts:	143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD2093E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		1,718.00 F	*1,400.00 F
F=Franchise part.						
Total Parts (S\$)					1,718.00	1,400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUNDRY	100.00	100.00
Sub Total (\$\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	235.20	214.20
2	SPRAY PAINTING	New	456.94	456.94
Gross Labour Cost (\$\$)			692.14	671.14

Report was unsubmitted during this print-out.

< END OF ESTIMATES >