

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

05 January 2021

MRO532EE1048526

TP Budget Direct
Xiao Chen.

QUOTATION FOR ACCIDENT REPAIR OF SLE5517A TOYOTA ALTIS THIRD PARTY INSURER: AUTO & GENERAL INSURANCE

S/No.	Parts List	Qty	Amount (\$)
1.	Front fender LH <i>Dented</i>	1	\$ 622.10 ✓ <i>585</i>
2.	Front fender inner shield LH <i>torn</i>	1	\$ 171.20 ✓
3.	Front fender "VVTI" emblem LH <i>new</i>	1	\$ 42.10 ✓
4.	Front bumper <i>Dented</i>	1	\$ 563.60 ✓
5.	Front bumper side retainer L/R <i>LH new</i>	2	\$ 110.40 <i>55.20</i>
6.	Front bumper seal <i>new</i>	1	\$ 52.50 +
7.	Front bumper fog lamp LH <i>new</i>	1	\$ 298.10 +
8.	Front bumper fog lamp garnish LH <i>new</i>	1	\$ 62.00 +
9.	Front bumper reinforcement beam <i>new</i>	1	\$ 393.90 +
10.	Front bumper lower grille <i>Crushed</i>	1	\$ 152.80 ✓
11.	Front grille <i>Crushed</i>	1	\$ 314.90 +
12.	Front grille "logo" emblem <i>new</i>	1	\$ 71.60 +
13.	Front support panel <i>new</i>	1	\$ 721.30 +
14.	Front brace panel <i>new</i>	1	\$ 115.70 +
15.	Front headlamp LH <i>Crushed</i>	1	\$ 713.80 ✓
16.	Air resonator assy <i>new</i>	1	\$ 240.10 +
Subtotal before discount			\$ 4646.10
Discount 25%			<u>\$ 1161.52</u>
Subtotal 1			\$ 3484.57

S/NETT

1.	Front no plate <i>new</i>	1	\$ 25 +
2.	Front no plate garnish <i>new</i>	1	\$ 50 +
3.	Front bumper clip <i>new</i>	1	\$ 30 ✓
4.	Front fender inner shield clip <i>new</i>	1	<u>\$ 30</u>

S/Nett Total \$ 135

LABOUR

To check front electrical wiring system

To straighten, repair, realign on rear affected area and replace damaged parts

To spray painting on affected area

Total Labour Cost

830
\$ 80 *30*
\$ 800 *400*
\$ 800 *400*
\$ 1680

Total Cost Of Repairs (Total cost of parts + Total labour cost)

\$ 5299.57

total: 2602.77
4s: 2K.
04 Days.