



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	TPVD TBC (SLF9511J)
Date of Loss	30 December 2020
Time of Loss	22.05
Loss Description	SMH7141J (INSD) > SLF9511J > SJR2851J
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="40226"/>
Nett Loss Amount	\$14,774.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SLF9511J	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>16/09/2016</div> <div></div>
Mileage	<div>81284</div>	Age of Vehicle	4

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2016</div>
Make	TPVD	<div>MAZDA</div>
		<div></div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	HARDIP SANUN	<div></div>
Date of Birth	5 February 1966	<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	TBC POLICY INFORMATION	MAZDA3 4-DOOR SED ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JM6BM42A8G0347355"/>
Engine No		<input type="text" value="P520377383"/>
Engine Capacity		<input type="text" value=""/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="55000"/>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Male	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S1779690I	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

05/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="20"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts












Add













Approve













Deny



Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER	Damaged	0	1062.2	No		20			849.76	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER L/R TOW HOOK COVERS	Missing	0	25	No		20			40	Reviewing
<input type="checkbox"/>		0	1		REAR O/S BUMPER REFLECTOR	Cracked	0	62.5	No		20			50	Reviewing
<input type="checkbox"/>		0	1		REAR N/S BUMPER REFLECTOR	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Bent	0	541.7	No		20			433.36	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER L/R SIDE RETAINERS	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER TOP CLIPS	Serviceable	0	0	No		20			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	<input type="checkbox"/>		0	2		REAR BUMPER TOP CLIPS HOLDERS	Serviceable	0	0	No				0	Deny
	<input type="checkbox"/>		0	1		REAR END PANEL	Dented	0	447.6	No				358.08	Reviewing
	<input type="checkbox"/>		0	1		REAR END PANEL INNER TRIM	Twisted	0	241.2	No				192.96	Reviewing
	<input type="checkbox"/>		0	1		REAR FLOOR SPONGE TRAYS	Damaged	0	220.4	No				176.32	Reviewing
	<input type="checkbox"/>		0	2		REAR L/R FENDER INNER SHIELD	Serviceable	0	0	No				0	Deny
	<input type="checkbox"/>		0	2		REAR L/R TAILLAMPS	Cracked	0	915	No				1464	Reviewing
	<input type="checkbox"/>		0	2		REAR L/R TAILLAMPS PANELS	Repair	0	0	No				0	Deny
	<input type="checkbox"/>		0	1		REAR SMART KEYLESS ANTENNA	Serviceable	0	0	No				0	Deny
	<input type="checkbox"/>		0	1		REAR BOOTLID	Dented	0	1053.3	No				842.64	Reviewing
	<input type="checkbox"/>		0	1		REAR BOOTLID LOGO	Necessary	0	65.8	No				52.64	Reviewing
	<input type="checkbox"/>		0	1		REAR BOOT EMBLEM 'MAZDA'	Necessary	0	58.2	No				46.56	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT EMBLEM '3'	Necessary	0	34.4	No		20			27.52	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT EMBLEM 'SKYACTIV'	Necessary	0	68.6	No		20			54.88	Reviewing
<input type="checkbox"/>		0	2		REAR BOOT LID LAMP L/R	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	2		REAR L/R BOOT LID LICENCE LAMP	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID INNER LOCK	Bent	0	153	No		20			122.4	Reviewing
<input type="checkbox"/>		0	1		REAR BOOT LID LOCK STICKER	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID INNER STICKER	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	2		REAR BOOT LID L/R HINGES	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID WEATHER STRIP	Twisted	0	124.6	No		20			99.68	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER	Deformed	0	1083.3	No		20			866.64	Reviewing
<input type="checkbox"/>		0	2		FRONT L-R BUMPER RETAINER	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER TOP PAD	Deformed	0	288.9	No		20			231.12	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	2		FRONT BUMPER L-R CHROME MOULDING	Damaged	0	186.9	No		20			299.04	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER TOP FRAME PAD	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER TOP BEAM	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER REFORMENT	Bent	0	466.8	No		20			373.44	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER REFORMENT PAD	Twisted	0	161.2	No		20			128.96	Reviewing
<input type="checkbox"/>		0	2		FRONT BUMPER L-R BRACKETS	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER LOWER GRILLE	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	2		FRONT BUMPER L-R FOG LAMPS	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	2		FRONT BUMPER L-R FOG LAMPS COVERS	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILL LOGO	Damaged	0	58.6	No		20			46.88	Reviewing
<input type="checkbox"/>		0	2		FRONT L-R HEADLAMP	Cracked	0	1889	No		20			3022.4	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT SUPPORT PANEL	Serviceable	0	0	No		20			0	Deny
<input type="checkbox"/>		0	1		FRONT CROSS MEMBER	Serviceable	0	0	No		20			0	Deny








Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TOWING	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE AND REFIX FRONT & REAR REVERSE SENSOR	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO RESPRAY UNDERCOATING	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIX INTERIOR TRIMS TO ASSIST REPAIR	0	80	0	0	Reviewing	
<input type="checkbox"/>		0		TO CHECK ELECTRICAL WIRING	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO RESPRAY PAINTING AND ETC	0	1400	0	0	Reviewing	
<input type="checkbox"/>		0		PANEL BEATING, CUT, WELD PANEL, REMOVE AND REPLACING ABOVE PARTS	0	1500	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve













Deny




Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 8 DAYS	Reviewing		0		
<input type="checkbox"/>		0	REAR REVERSE CAMERA	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	SET REAR BUMPER PDC SENSOR	Reviewing		200	SHORTED	

SET REAR  
.....

.....

<input type="checkbox"/>	 EDIT	SR NO	NUMBER NAME WITH CASING	Deny ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	NOT COMMENT NECESSARY	 REMOVE
<input type="checkbox"/>		0	REAR TAILLAMP SIDE CLIPS - 4PCS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	REAR EXHAUST MOUNTINGS - 2PCS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	REAR FENDER INNER TRIM CLIPS - 10PCS	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	SET REAR BUMPER CLIPS	Reviewing		27	NECESSARY	
<input type="checkbox"/>		0	REAR BOOT INNER TRIM CLIPS	Deny		0	NOT NECESSARY	

EDIT		SR NO	CLIPS - 10PCS NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	NECESSARY COMMENT	REMOVE
<input type="checkbox"/>								
<input type="checkbox"/>								
<input type="checkbox"/>		0	SET FRONT BUMPER PDC SENSOR	Deny		0	NOT NECESSARY	
<input type="checkbox"/>								
<input type="checkbox"/>		0	SET FRONT BUMPER CLIPS	Reviewing		45	NECESSARY	
<input type="checkbox"/>								
<input type="checkbox"/>		0	SET FRONT NUMBER PLATE WITH CASING	Reviewing		40	SCRATCHED	





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$13,211.28	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$9,779.28			
Labour		\$0.00		\$3,120.00			
Miscellaneous		\$0.00		\$312.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	10500		



Submit for Review