

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5334M*Not Authored***AAD2012-203***Resurvey B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

30 DEC 2020**SHD5334M**

JTDKB3FU103078820

TOYOTA

PRIUS

29/12/2020

TOKIO

11/01/2019

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS AND BODY, REAR LAMP, RH
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, REAR FLOOR (CTR)

LIST

\$	Bu	442.60	✓
\$	R	332.70	✓
\$	R	576.30	✓
\$	M	15.40	✓
\$	S	116.50	X
\$	O	117.70	✓
\$	M	123.70	✓
\$	S	88.50	X
\$	S	88.50	X
\$	S	451.80	X
\$	S	502.00	X
\$	R	650.30	X
\$	S	175.10	X
\$	S	241.90	X
\$	S	229.90	X

TOTAL \$ 4,152.90**25% \$ 1,038.23****\$ 3,114.68****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
 - 1 REAR BUMPER PROTECTOR
- 1SET REAR FENDER LINER CLIP
- 1SET REAR BUMPER RETAINER CLIP
 - 1 REAR NUMBER PLATE WITH HOLDER
- 1SET TAILLAMP LOWER CLIP
- 1SET TAILLAMP UPPER CLIP

\$	Shon	700.00	250JA
\$	na	95.00	60JA
\$	na	180.00	30JA
\$	na	85.00	X
\$	na	85.00	X
\$	S	140.00	X
\$	na	55.00	X
\$	na	55.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5334M**AAD2012-203****1 END PANEL TRIM CLIP**

\$	65.00	X
TOTAL	\$ 1,460.00	

TOTAL PARTS	\$ 4,574.68
--------------------	--------------------

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	380.00	X
----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	2,200.00	400
----	----------	-----

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	380.00	X
----	--------	---

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$	180.00	X
----	--------	---

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$	480.00	X
----	--------	---

TOTAL

To transfer of Fender fittings, attachments and perform water seepage test.

Over All Total	\$ 480.00	X
-----------------------	------------------	---

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$	380.00	X
----	--------	---

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$	380.00	X
----	--------	---

To check steering geometry and computer wheel alignment

\$	220.00	X
----	--------	---

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	250.00	X
----	--------	---

Towing Fees

\$	150.00	X
----	--------	---

Trans-cab Auto Services Pte Ltd**AAD2012-203**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5334M

Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	500/
To reinstall rear bumper parking sensor.	\$	170.00	50/
To Check Electrical Lighting Concerned.	\$	170.00	15/
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 220.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To lift-up / out engine with gear box and refit.	\$	4 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	4 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	4 380.00	X
TOTAL	\$	9,990.00	
Over All Total	\$	14,564.68	

(PART-BY-PART) Repair Days**25 DAYS****3 day,**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: