



CYCLE & CARRIAGE

AIG - OD CLAIM  
SURVEY: 05/01/21  
LKK - STEVE

VEHICLE NO : SMP6894J

MODEL : MIT/OUTLANDER 2.0

WIP : 61480

Material	:	\$	<u>6,037.57</u>
Labour	:	\$	<u>4,770.00</u>
Sub-Total	:	\$	<u>10,807.57</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>10,507.57</u>
GST 7%	:	\$	<u>735.53</u>
Grand Total	:	\$	<u>11,243.10</u>
Finalise By/Date	:	<u>AMM ON 26/01/21</u>	

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS + 4 days (week ends)



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  06/01/2021	Cust No/Name	KCV12241/ZHUO YONGZHONG
	Reg No/Reg Date	SMP6894J*#*T2/ 10/10/2019
	Date In/Mileage	21/01/2021/ 16058
	Chassis/Package	GF7W0601719 /BP
	Engine No	4J11BD7753
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	26/01/2021/ 10:51	BLE	884 / Lauro Songcuan	61480

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, BONNET, FRONT SUPPORT, LH FRONT FENDER AND LH FRONT DOOR, REPAIR LH FRONT WHEELHOUSE				2250.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER, BONNET, FRONT SUPPORT, LH FRONT FENDER, LH FRONT DOOR & LH "A" PILLAR				2100.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY SUPPLY BODY PANEL SEALANT				60.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY LABOUR FOR INSTALLATION OF RIM D/N NO:313934				30.00 ✓
X EXC EXCESS				-300.00
X FACE,FR BUMPER ✓	1.00	1048.00	23.00	806.96 ✓
X GARNISH,FR BUMPER,LH ✓	1.00	48.00	23.00	36.96 ✓
X BRACKET,FR BUMPER SIDE,LH ✓	1.00	18.00	23.00	13.86 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	48.00	23.00	36.96 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	112.00	23.00	86.24 ✓
X HOOD ✓	1.00	975.00	23.00	750.75 ✓
X TAPE, BONNET ✓	1.00	4.00	23.00	3.08 ✓
X ENGINE HOOD EMBLEM ✓	1.00	80.00	23.00	61.60 ✓

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

**THIS IS NOT AN OFFICIAL TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  06/01/2021	Cust No/Name	KCV12241/ZHUO YONGZHONG
	Reg No/Reg Date	SMP6894J*#*T2/ 10/10/2019
	Date In/Mileage	21/01/2021/ 16058
	Chassis/Package	GF7W0601719 /BP
	Engine No	4J11BD7753
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	26/01/2021/ 10:51	BLE	884 / Lauro Songcuan	61480

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FENDER,FR LH ✓	1.00	688.00	23.00	529.76 ✓
X SHIELD,FR WHEELHOUSE,LH ✓	1.00	164.00	23.00	126.28 ✓
X PNL,HEADLAMP SUPT,UPR LH ✓	1.00	58.00	23.00	44.66 ✓
X MOULDING,FR BUMPER,LH ✓	1.00	116.00	23.00	89.32 ✓
X MOULDING,FR WHEEL ARCH,LH ✓	1.00	160.00	23.00	123.20 ✓
X COVER,FR DECK,LH ✓	1.00	19.00	23.00	14.63 ✓
X TAPE,FR DOOR SASH,LH ✓	1.00	42.00	23.00	32.34 ✓
X TAPE,RR DOOR SASH ✓	1.00	42.00	23.00	32.34 ✓
X PANEL ASSY,FR DOOR,LH ✓	1.00	977.00	23.00	752.29 ✓
X HEADLAMP ASSY,LH ✓	1.00	1938.00	23.00	1492.26 ✓
X WHEEL,DISC LHF ✓	1.00	974.00	23.00	749.98 ✓
X TAPE,BONNET ✓	3.00	4.00	23.00	9.24 ✓
X INSULATOR,FR FENDER,LH ?	1.00	60.00	23.00	46.20 ?
X PAD,FR FENDER → <i>supp.</i>	1.00	38.00	23.00	29.26 X
Z TEXT				

OD CLAIM - AIG  
SURVEY: STEVE (LKK) 05.01.2021  
DOA: 05.01.2021  
12 DAYS

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	6,037.57		Nett	10,507.57
Labour	4,620.00	7% GST on	10507.57	735.53
Standard Menu	0.00			
Specialist Job	30.00			
Diagnostics Job	0.00		<b>Total Payable</b>	<b>11,243.10</b>
Sundry/Others	-180.00			
Total(w/o GST)	10,507.57			

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMP 6894 J**

<b><u>Materials</u></b>		<b><u>Cost \$</u></b>
1	Pad, FR Fender	38.00 / MIS
	23% Discount	<u>8.74</u>
		<u>29.26</u>
	7% GST	2.05
	<b>Total</b>	<b><u>31.31</u></b>

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan  
Customer Service  
Cycle & Carriage  
Pandan Gardens

CAR NO: shp 68945

WIP: 61480

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	INSULATOR	? / SUPP		✓ CEU	5220m 299
2	Pos.	? / SUPP		✓ M115 (Smp)	5220 K001
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	11.11.20	Steve
PHOTO AFTER PAINT	14/12/21	
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDER

SURVEYOR: STEVE

Work Order: R001302  
 License: SMP 6894 J  
 Technician: 106 WENG SOON  
 Mileage: 16058  
 Date: 7.1.21 11:02

**Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive**

**Front : Left**

Actual	Before	Specified Range
0°00'	0°01'	-0°10' 0°50'
2°17'	2°17'	2°05' 3°05'
0°02'	-0°02**	-0°02' 0°06'
12°54'	12°54'	11°15' 14°15'
12°54'	12°54'	11°05' 15°05'

**Front : Right**

Actual	Before	Specified Range
0°12'	0°12'	-0°10' 0°50'
3°04'	3°04'	2°05' 3°05'
0°01'	0°04'	-0°02' 0°06'
13°04'	13°03'	11°15' 14°15'
13°15'	13°15'	11°05' 15°05'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

**Front**

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
-0°12'	-0°12'	-0°30' 0°30'
-0°46**	-0°46**	-0°30' 0°30'
-0°09'	-0°10'	
0°04'	0°02'	-0°04' 0°12'

**Rear : Left**

Actual	Before	Specified Range
-0°53'	-0°54'	-1°15' 0°15'
0°06'	0°03'	0°02' 0°12'

**Rear : Right**

Actual	Before	Specified Range
-1°09'	-1°10'	-1°15' 0°15'
0°07'	0°04'	0°02' 0°12'

Camber  
 Toe

**Rear**

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
0°15'	0°16'	-0°30' 0°30'
0°13'	0°08'	0°04' 0°24'
0°00'	-0°01'	

Work Order: R001302  
 License: SMP 6894 J  
 Technician: 106 WENG SOON  
 Mileage: 16058  
 Date: 7.1.21 11:02

Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive

Front : Left

Actual	Before	Specified Range
0°00'	0°01'	-0°10' 0°50'
2°17'	2°17'	2°05' 3°05'
0°02'	-0°02'	-0°02' 0°06'
12°54'	12°54'	11°15' 14°15'
12°54'	12°54'	11°05' 15°05'

Front : Right

Actual	Before	Specified Range
0°12'	0°12'	-0°10' 0°50'
3°04'	3°04'	2°05' 3°05'
0°01'	0°04'	-0°02' 0°06'
13°04'	13°03'	11°15' 14°15'
13°15'	13°15'	11°05' 15°05'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
-0°12'	-0°12'	-0°30' 0°30'
-0°46'	-0°46'	-0°30' 0°30'
-0°09'	-0°10'	
0°04'	0°02'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-0°53'	-0°54'	-1°15' 0°15'
0°06'	0°03'	0°02' 0°12'

Rear : Right

Actual	Before	Specified Range
-1°09'	-1°10'	-1°15' 0°15'
0°07'	0°04'	0°02' 0°12'

Camber  
 Toe

Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
0°15'	0°16'	-0°30' 0°30'
0°13'	0°08'	0°04' 0°24'
0°00'	-0°01'	

All DTCS

*SMP68045*  
*Before using MOT-3x VOT unit to check all the sand*

Item	Setting
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS	
AT/CVT/A-MT/T-C-SST	CVT_14080300		No DTCS	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCS	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS	
SRS-AIR BAG	ORC_81047302		No DTCS	
Air Conditioner	AC_80080011		No DTCS	
ETACS	ETACS_83040801	B16A2	Turn signal(LH) bulb outage	Stored
Meter	MTR_84084001		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCS

2021.01.20

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCS	
OSS	OSS_9588000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B178
Vehicle Information		DBA-GFTW 2019MY

SMP68945  
After using MOTOR for unit to force all the sand  
to be done

2021.01.20

All DTCS

2021.01.20

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCS	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCS	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS	
SRS-AIR BAG	ORC_81047302		No DTCS	
Air Conditioner	AC_80080011		No DTCS	
ETACS	ETACS_83040801		No DTCS	
Meter	MTR_84084001		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCS

2021.01.20

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCS	
OSS	OSS_9588800B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	