

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

04/01/2021

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- **XA018**

Page # :- 1

Veh # :- SKE8317C

Veh Model :- HONDA JAZZ 1.3L A

Estimate# :- CK421391

Claim # :-

ACC. Date :- 31/12/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	REAR BOOT <i>bt</i>	1	PC	971.50	971.50
2.	REAR BOOT EMBLEM "JAZZ" <i>per</i>	1	PC	68.20	68.20
3.	REAR BOOT LOCK <i>XSVL</i>	1	PC	289.50	289.50 X
4.	REAR BOOT RUBBER <i>re</i>	1	PC	129.30	129.30
5.	REAR BOOT TRIM CLIPS <i>per</i>	8	PC	3.90	31.20
6.	TAILLAMP LH <i>2 crn</i>	1	PC	299.20	299.20
7.	REAR PANEL <i>repair</i>	1	PC	376.50	376.50 X
8.	REAR PANEL TRIM <i>2 crn</i>	1	PC	90.80	90.80
9.	REAR BUMPER <i>di</i>	1	PC	597.50	597.50
10.	REAR BUMPER CLIPS <i>re</i>	10	PC	3.90	39.00
11.	REAR BUMPER RETAINER L+R <i>XSVL</i>	2	PC	26.50	53.00 X
12.	REAR WINDSCREEN MOULDING <i>re</i>	1	SET	313.20	313.20
LIST TOTAL S\$					3,258.90
20% DISCOUNT S\$					-651.78
					2,607.12

2539.90

20%

2031.92

260

SPECIAL NET ITEMS :

1.	REA BUMPER SENSOR <i>7.1w</i>	1	PC	220.00	220.00
2.	REAR NUMBER PLATE <i>XSVL</i>	1	PC	35.00	35.00 X
3.	REAR WINDSCREEN SEALANT <i>re</i>	1	PC	80.00	80.00

SPECIAL NET TOTAL S\$

335.00

LABOUR :

TO CUT & WELD REAR END PANEL TO REPAIR REAR
FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS
MEMBER, TO REMOVE & REFIX DAMAGED PARTS
STRAIGHTEN & REALIGN AFFECTED AREAS

TO SPRAY AFFECTED AREAS

TO REMOVE & REFIX REAR WINDSCREEN GLASS

TO REMOVE & REFIX REAR BOOT MACHANISM CHECK
& TEST UP WIPER MOTOR & CENTRE LOCKING SYSTEM

TO REMOVE & REFIX REAR LAGGAGE COMPARTMENT
SIDE COVER, SIDE GARNISH & OTHER ATTACHMENT
PARTS

TO INSTALL REVERSE SENSOR & CHECK WATER
SEEPAGE

TO RUST PROOF AFFECTED AREAS

LABOUR TOTAL S\$

500 650.00

600 750.00

120 180.00

nn X 80.00

60 80.00

1360 40 60.00

1,840.00

imate

1/2021

MPO INSURANCE SINGAPORE PTE LTD
RAFFLES PLACE
01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

ention :- XA018

Page # :- 1 139947
Veh # :- SKE8317C
Veh Model :- HONDA JAZZ 1.3L A
Estimate# :- CK421391
Claim # :-
ACC. Date :- 31/12/20
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 4,782.12

GST @ 7 % 334.75

AMOUNT DUE S\$ 5,116.87

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

5 days

45

11/01/2021 @ 1350

Resurvey after repair

2031.92

260.00

1360.00

3651.92

20%

2921.53

45-21900

5 days