

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM LEE KEONG
17 LENTOR GROVE

SINGAPORE 789191

TEL: 91190017

ATTN:

Your Ref No: SLX531R

Claim Type: Third Party

Accident Date: 28/12/2020

TP Veh Reg No: EB120S

Estimate No: MC1901653

Date: 29 Dec 2020

Policy No: PNPV2020-00009706

Veh Reg No: SLX531R

Make/Model: MAZDA 6 SEDAN 2.0 AT

Estimate Repair Cost to Vehicle No :SLX531R

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP LH	1 PC	963.50	
2 FRONT BUMPER	1 PC	1,151.30	
3 FRONT BUMPER SIDE RETAINER LH	1 PC	14.70	
4 FRONT BUMPER CLIPS	15 PC	45.00	
5 FRONT FENDER LH	1 PC	383.70	
6 FRONT FENDER COWLING LH	1 PC	102.90	
7 FRONT FENDER COWLING CLIPS	8 PC	24.00	
8 FRONT FENDER BRACKET LH - CHECK PRICE	1 PC	0.00	
9 FRONT WHEEL BEARING W HUB LH	1 PC	566.70	
10 FRONT KNUCKLE ARM LH	1 PC	407.10	
11 FRONT LOWER ARM LH	1 PC	259.10	
12 FRONT SHOCK ABSORBER LH	1 PC	301.20	
13 FRONT SHOCK ABSORBER TOP MOUNTING LH	1 PC	96.50	
14 FRONT STABILISER LINKAGE LH	1 PC	70.80	
		4,386.50	
	Less 20%	877.30	3,509.20
Special Nett			
15 SPORT RIM LHF	1 PC	1,197.70	
16 TYRE LHF - CHECK PRICE	1 PC	0.00	
		1,197.70	1,197.70
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
18 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
19 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	280.00	
20 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT BONNET INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
21 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH,FRONT DOOR LH.	1 PC	700.00	
		1,700.00	1,700.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM LEE KEONG
17 LENTOR GROVE

SINGAPORE 789191

TEL: 91190017

ATTN:

Your Ref No: SLX531R

Claim Type: Third Party

Accident Date: 28/12/2020

TP Veh Reg No: EB120S

Estimate No: MC1901653

Date: 29 Dec 2020

Policy No: PNPV2020-00009706

Veh Reg No: **SLX531R**

Make/Model: MAZDA 6 SEDAN 2.0 AT

Estimate Repair Cost to Vehicle No :SLX531R

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 6,406.90
Add GST @ 7%			448.48
Total Amount Payable			S\$ 6,855.38

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED FIFTY FIVE AND CENTS THIRTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 533C

Vehicle Details

Vehicle No.: SLX531R
Vehicle to be Exported: No
Intended Deregistration Date: 28 Dec 2020
Vehicle Make: MAZDA
Vehicle Model: MAZDA6 SEDAN 2.0 AT STANDARD EU6
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: PE21020626
Chassis No.: JM6GL1071J0135311
Maximum Power Output: 121.0 kW (162 bhp)
Open Market Value: \$19,174.00
Original Registration Date: 14 Mar 2018
First Registration Date: 14 Mar 2018
Transfer Count: 0
Actual ARF Paid: \$19,174.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Mar 2028
PARF Rebate Amount: \$14,380.00

Intended COE Rebate Details

COE Expiry Date: 13 Mar 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$39,001.00
COE Rebate Amount: \$28,098.00
Total Rebate Amount: \$42,478.00

The information contained herein is correct as at 28 Dec 2020

OK