



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21000150/Uqd3e2	
			Date: 01/02/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 9601U	Veh. Inspected	4987S	
Policy No.	D20MTPV01009080	Coverage (\$)	0.00	
Claim No.	CMTD2003840/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	04/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HINO 700	c.c	12913	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JHDFS1EKNXXX10095	Colour	WHITE / YELLOW	
Odometer	272 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	9 mm	
R/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	9/9/9/9 mm	
L/H Rear Tyre	295/80 R22.5 (D/D)	BRIDGESTONE	9/9/9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/12/2020	Inspection Date	06/01/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	