



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|-----------------------------|--|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS/SMO21000151/GUtd3e2 | |
| | | | Date: 12/04/2021 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBD 9479Z | Veh. Inspected | SLX 1982R | |
| Policy No. | D20MTPCVE002220 | Coverage (\$) | 0.00 | |
| Claim No. | CMTD2100032/MYE | Excess (\$) | 0.00 | |
| Assign From | GRACE TEO | Assign Date | 05/01/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA ALPHARD 2.5 | c.c | 2494 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | JTNGF3DH708008818 | Colour | BLUE | |
| Odometer | 172539 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 235/50 R18 | YOKOHAMA | 6 mm | |
| L/H Front Tyre | 235/50 R18 | YOKOHAMA | 6 mm | |
| R/H Rear Tyre | 235/50 R18 | YOKOHAMA | 6 mm | |
| L/H Rear Tyre | 235/50 R18 | YOKOHAMA | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 02/01/2021 | Inspection Date | 06/01/2021 | |
| Survey held at | FREESION AUTODRIVE 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #03-33 SINGAPORE 417800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |