



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHANG SER SAN Reg No/Reg Date SMR526B / 17/12/201 Date In/Mileage / 5987 Chassis No MMBSTA13AKH002544 Engine No 3A92UHX6618 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount	
KAX00008	Credit	05/01/2021/ 13:13	QUD	247 / DonBong	61481				3600.00	
Description of Goods / Services										
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER, CUT/WELD LH REAR FENDER, LH TAILAMP HOUSING, REAR END PANEL REPAIR LH REAR DOOR, REMOVE AND INSTALL LH SKIRTING TO FACILITATE REPAIR WORK							5 x 450		2250
E PNT88000	REMOVE AND REPLACE REAR WINDSCREEN (CUT SCRATCHES LINE)									240.00
M SUNDRY	SUPPLY REAR WINDSCREEN SEALANT									80.00
E PNT88000	REMOVE AND INSTALL REAR CABIN TO FACILITATE REPAIR WORK									(photo) 120.00
E PNT88000	REMOVE AND INSTALL REAR PARKING ASSIST									60.00
M SUNDRY	REPLACE REAR WINDSCREEN SOLAR FILM									220.00
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR BUMPER, REAR BODY KITS, REAR BOOT LIP, LH REAR FENDER, FUEL CAP COVER, LH REAR DOOR, REAR TAILAMP HOUSING, REAR SPOILER LIP AND AFFECTED PORTION							112 6.5 x 350		3150.00
M SUNDRY	APPLY BODY SEALANT									2275
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									80 160.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									30.00
M SUNDRY	LABOUR RENEW SPORT RIM INCLUDING BALANCING									30.00
M SUNDRY	SUPPLY LH REAR TIRES									! 280.00
M SUNDRY	PERFORM RUST PREVENTION									40 20 160.00
A WHEELALIGNMENTBP										120.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	/CHANG SER SAN / 17/12/201 / 5987 MMBSTA13AKH002544 3A92UHX6618 MIT/19MY ATTRAGE 1.2 CVT A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	05/01/2021/ 13:13	QUD	247 / DonBong	61481

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
To Conduct Computerize Full Wheel Alignment				(photo) 450.00 ✓
A 13900099 REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIR WORK				450.00 X
A 34900099 TO RENEW REAR U/CARRIAGE DAMAGES				40.00 ✓
M SUNDRY SUPPLY C&C LOGO				220.00 X
M SUNDRY SUPPLY PARKING SENSOR				20 50.00
M SUNDRY SUNDRIES	1.00	425.00	23.00	327.25
M PANEL,RR END <i>DD</i>	1.00	755.00	23.00	581.35
M PANEL,QTR,OTR LH <i>DD</i>	1.00	60.00	23.00	46.20
M PANEL,RR COMB LAMP HSG,LH <i>DD</i>	1.00	118.00	23.00	90.86
M EXTN,QTR PANEL,UPR OTR,LH <i>DD</i>	1.00	126.00	23.00	97.02
M REINF,RR PILLAR,LH <i>X NN</i>	1.00	228.00	23.00	175.56
M PANEL,QTR,LWR INR LH <i>? X NN</i>	1.00	48.00	23.00	36.96
M LID,FUEL FILLER <i>X R</i>	1.00	3.00	23.00	2.31
M CLIP,FUEL FILLER LID LOCKI <i>REC</i>	1.00	544.00	23.00	418.88
M GLASS,RR WINDOW <i>X NN</i>	2.00	3.00	23.00	4.62
M STOPPER,WINDSHIELD GLASS <i>REC</i>	3.00	9.00	23.00	20.79
M SPACER,RR WINDOW <i>REC</i>	1.00	335.00	23.00	257.95
M LAMP ASSY,COMB,RR LH <i>BR</i>	2.00	3.00	23.00	4.62
M GROMMET,TAIL LAMP <i>REC</i>	2.00	3.00	23.00	4.62
M GROMMET,TAIL LAMP <i>REC</i>	1.00	23.00	23.00	17.71
M LH REFLECTOR <i>X NN</i>	1.00	66.00	23.00	50.82
M TRIM,RR END <i>X NN</i>	1.00	160.00	23.00	123.20
M TRIM,TRUNK ROOM SIDE,LH <i>CRU</i>	1.00	69.00	23.00	53.13
M MARK,THREE-DIA <i>REC</i>	1.00	21.00	23.00	16.17
M MARK,ATTRAGE <i>REC</i>	1.00	157.00	23.00	120.89
M WEATHERSTRIP,TRUNK LID <i>CRU</i>	1.00	20.00	23.00	15.40
M STRIKER,TRUNK LID LATCH <i>X NN</i>	1.00	218.00	23.00	167.86
M LATCH,TRUNK LID <i>X NN</i>				

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



Co Reg No : 1977014696

GST Reg No : MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892		/CHANG SER SAN	
Cust No/Name	Reg No/Reg Date	SMR526B	/ 17/12/201
Date In/Mileage		/	5987
Chassis No	MMBSTA13AKH002544		
Engine No	3A92UHX6618		
Make/Model	MIT/19MY ATTRAGE 1.2 CVT		
Colour/Trim	A06 COOL SILVER MET/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	05/01/2021/ 13:13	QUO	247 / DonBong	61481

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BRACKET,RR BUMPER,LH <i>BR</i>	1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH <i>X NN</i>	1.00	28.00	23.00	21.56
M CLIP,FR BUMPER <i>ARC</i>	6.00	4.00	23.00	18.48
M FACE,RR BUMPER <i>BR</i>	1.00	748.00	23.00	575.96
M ATTRAGE BODYKITS <i>X (Salvage from SMR 6242) (oken)</i>	1.00	1643.00	00.00	1643.00
M WHEEL,DISC <i>X NAI</i>	1.00	687.00	23.00	528.99
M DRUM ASSY,RR BRAKE <i>X NN</i>	1.00	259.00	23.00	199.43
M DECAL,MIVEC <i>ARC</i>	1.00	36.00	23.00	27.72

Estimate

SURVEYOR NAME: Steve CLKK 5/1/20, 3.00pm

SURVEYOR SIGNATURE: DD- NM Aut

DATE: EXCESS - ?

REMARKS: PIP
Ry BL JS
13 days

Confirm & accepted by _____ Authorized signatory and company stamp	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Net 15,250.87 7% GST on 15250.87 1067.56 Total Payable 16,318.43
---	--	---

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.