

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 14 Jan 2021

## **Preliminary Advice**

Insured Vehicle No : SFQ8910K  
TP Vehicle No : SFK14G  
Make : AUDI A8 L  
Date of Inspection : 12/01/2021  
Inspection At : KAIZEN MOTORS PTE LTD (HQ)  
68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT  
SINGAPORE 417896

Accident Date : 30/12/2020  
Assignment Date : 05/01/2021  
Est. Duration of Repair : 4

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,996.94
Revised Amount	:S\$	5,643.12
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,643.12
Lump Sum Repair	:S\$	4,500.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Survey on WP