



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHIEW AI JUAN (JIANG AIJUAN)	Cust No/Name	LCV08947/CHIEW AI JUAN (JIANG AIJUAN)
BLK 288 BISHAN STREET 24	Reg No/Reg Date	SMJ7715T / 20/03/201
#15-07	Date In/Mileage	/ 0
SINGAPORE 570288	Chassis No	KNAD6811VK6244907
Contact No	Engine No	G3LCJP143385
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	UD CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV08947	CRDVCH	05/01/2021/ 11:39		442 / CocoLu	26774			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00
RENEW FRT BUMPER, BONNET, FRT SUPPORT PANEL, REPAIR FRT FENDER RH								
E PNT98000								1050.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
Sundry								
E PNT88000								100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								80.00
TOP UP AIRCON GAS								
M COVER-FR BUMPER UPR					1.00	476.00	00.00	476.00
M SKID PLATE-FR BUMPER					1.00	55.00	00.00	55.00
M LIP ASSY-FRONT BUMPER					1.00	32.00	00.00	32.00
M COVER-RADIATOR GRILLE UPR					1.00	46.00	00.00	46.00
M COVER-FR BUMPER FOG LAMP,RH					1.00	64.00	00.00	64.00
M LAMP ASSY-FRONT FOG,RH					1.00	234.00	00.00	234.00
M AIR DUCT-FR BUMPER,RH					1.00	38.00	00.00	38.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	98.00	00.00	98.00
M BRACKET-FR BUMPER SIDE,RH					1.00	13.00	00.00	13.00
M COVER-FR BUMPER,LWR					1.00	367.00	00.00	367.00
M STIFFNER-FR BPR LWR					1.00	123.00	00.00	123.00
M PANEL ASSY-HOOD					1.00	904.00	00.00	904.00
M BEAM COMPLETE-FR BUMPER					1.00	544.00	00.00	544.00
M CARRIER ASSY-FRONT END MODULE					1.00	556.00	00.00	556.00
M ORNAMENT-KIA NO.115					1.00	32.00	00.00	32.00
M GUARD ASSY-FRONT WHEEL,RH					1.00	56.00	00.00	56.00
M RESERVOIR & PUMP ASSY-WASHER					1.00	152.00	00.00	152.00
M LAMP ASSY-HEAD,RH					1.00	1845.00	00.00	1845.00

Confirm & accepted by

	Nett	8,635.00
7% GST on	8635.00	604.45
Total Payable		9,239.45

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.