

ASS. REC. BY:

REF:

ARG / 21000160/K6

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

1 1/2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H 59706

Yr Regn:

12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

532815

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL 15AUC 280989

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F: Sailun 215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

31/12/20

D.O.I.

4/1/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/11 61 Imp @ 1200

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5970G**AAD2012-***Not Authored
1/12/2001*

Vehicle No.:

Chassis No.:

04 JAN 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC5970G

VF1ABL15AUC280989

RENAULT

LATITUDE

31/12/2020

AIG

18/12/2014

PART

- | | |
|---|-------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMPER BRACKET SIDE LH REAR |
| 5 | 1 BUMPER BRACKET SIDE RH REAR |
| 6 | 1 BUMPER RETAINER LH REAR |
| 7 | 1 BUMPER RETAINER RH REAR |
| 8 | 1 BUMPER BEAM REAR |

LIST

\$	<i>Bur</i>	561.70	✓
\$	<i>Ad/LR</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	82.10	X
\$	<i>SL R</i>	54.20	X
\$	<i>SL</i>	59.80	X
\$	<i>R</i>	547.80	X
\$		1,896.40	
10% \$		189.64	
\$		1,706.76	

Special Nett

- | | |
|---|-------------------------------------|
| 1 | 1SET PARKING AID |
| | 1SET REAR BUMPER CLIP |
| | 1SET BUMPER BRACKET CTR CLIP |
| | 1SET BUMPER BRACKET SIDE CLIP RH RR |
| | 1SET BUMPER RETAINER RH CLIP RR |
| | 1SET BUMPER LOWER REAR RIVET |
| | 1SET BUMPER LOWER REAR CLIP |

\$	<i>SL</i>	700.00	X
\$	<i>SL</i>	66.00	✓
\$	<i>SL</i>	33.00	X
\$	<i>SL</i>	10.00	X
\$	<i>SL</i>	20.00	X
\$	<i>SL</i>	22.00	X
\$	<i>SL</i>	66.00	✓
TOTAL \$		917.00	
TOTAL PARTS \$		2,623.76	

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00

2201

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5970G

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>801</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>5</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>5</i> 170.00	<i>X</i>

TOTAL \$ 7,070.00**Over All Total \$ 11,400.52****(LUMP SUM)****Repair Days***20 DAYS*
1 1/2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5970G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Dec 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002441
Chassis No.:	VF1ABL15AUC280989
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$8,123.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$12,673.00
Total Rebate Amount:	\$20,796.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 Dec 2020

OK