

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21000165/ATD3N2**Date:** 04/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00019842001	
Claimant Vehicle No :	SMN5421H	Insured Vehicle No :	GBE9067Z	
Date of Loss:	04/01/2021	Nature of Claim:	TP	Claim No: SNM21D200013/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5421H		Engine No:	G4FGKU152380
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)		Chassis No:	KMHD841CMKU915909
Reg. Date:	16/08/2019 (Man. Year: 2019)		Odometer:	25117 km
Colour:	Red			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,508.20	2,134.00	374.20	14.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,330.00	1,040.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	4,878.20	3,464.00	1,414.20	28.99

INSPECTION

Date of Assignment:	08/01/2021	
Date Inspected:	06/01/2021	Inspected At: Fong Motors (HQ) 1 Kaki Bukit Ave 6 #01-45, Autobay@ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
Parts:	143	HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN5421H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	574.40 FL	*574.40 FL
2	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	28.80 FL	*- FL
3	1		*FRONT BUMPER TOWING COVER	Not Necessary	12.80 FL	*- FL
4	1		*FRONT BUMPER SIGNAL LAMP RH	Not Necessary	184.80 FL	*- FL
5	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	82.80 FL	*- FL
6	1		*FRONT BONNET RUBBER MOULDING	Not Necessary	64.80 FL	*- FL
7	1		*FRONT HEADLAMP RH	Cut	1,298.80 FL	*1,298.80 FL
8	1		*FRONT GRILLE ASSY	Cracked	592.20 FL	*592.20 FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
11	1		*SET FRONT NO PLATE	Not Necessary	45.00 FS	*- FS
12	1		*NO PLATE GARNISH	Cracked	32.80 FL	*32.80 FL
13	1		*BUMPER SPONGE	Cracked	131.80 FL	*131.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,109.00	2,660.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	600.80	526.00
Total Parts (\$\$)	2,508.20	2,134.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE,REPLACE/OR REPAIR TO RECTIFY FRONT & PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT	New	120.00	30.00
2	TO RESPRAY,PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
3	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE DAMAGED BODYPARTS,REPAIR,ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	750.00	600.00
4	PAINT PROTECTION	New	500.00	200.00
Gross Labour Cost (\$)			2,370.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >