

FONG MOTORS

1 Kaki Bukit Ave 6 Blk C #01-27/45, AutoBay@ Kaki Bukit Singapore 417883

Tel: 6747 6388, Email: fongmotors@gmail.com

Company Reg No. 068972/00L

LEE CHENG KWOK

BLK 542 CHO A CHU KANG ST 52 #06-54

Singapore 680542

TP Ching
Denise**Estimate**

Code:

Date

Vehicle No.

Model

CHASSIS/ENG#

6 Jan 2021

SMH5421H SMN5421H.

HYUNDAI AVANTE

KMHD841CMKU915909

S/N	Particular	Quantity	Unit Price	Amount
LIST PRICE				
1	FRONT BUMPER <i>delid</i>	1		574.40 \$-00 ✓
2	FRONT BUMPER SIDE RETAINERS L/R <i>new</i>	2		28.80 \$-00 +
3	FRONT BUMPER TOWING COVER <i>new</i>	1		12.80 \$-00 +
4	FRONT BUMPER SIGNAL LAMP RH <i>new</i>	1	2465.40	184.80 \$-00 +
5	FRONT FENDER INNER SHIELD RH <i>new</i>	1		82.80 \$-00 +
6	FRONT BONNET RUBBER MOULDING <i>new</i>	1	1972.32	64.80 \$-00 +
7	FRONT HEADLAMP RH <i>at</i>	1		1298.80 \$-00 ✓
8	FRONT GRILLE ASSY <i>curled</i>	1		592.20 \$-00 ✓
SUBTOTAL BEFORE DISCOUNT				\$-00
PERCENTAGE DISCOUNT 20%				\$-00
Sub-total 1				\$-00
SPECIAL NETT				
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$30.00	\$30.00 ✓
2	REAR FENDER INNER SHIELD CLIPS <i>30</i>	1	\$30.00	\$30.00 +
Sub-total 2				\$60.00
LABOUR				
1	To diagnose, replace/or repair to rectify front & portion electrical system for proper functioning and where consistent to the accident	1	\$120.00	\$120.00 30
2	To respray, painting on the change bodyparts, repair portion and where consistent to the accident	1	\$1,000.00	\$1,000.00 300
3	To provide labour, workmanship to change damaged bodyparts, repair, align body structure & damaged and where consistent to the accident	1	\$750.00	\$750.00 600
Labour Total				\$1,870.00
Parts & Labour Total				\$1,930.00

A Paint Protection.

500
200

4769.4

Admin Lj
P/P 06/01/21
04 Days

Supplementary: 131.68

total 3464
(TP/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. SMH5421H
Make/Model HYUNDAI AVANTE
Year
Chassis No. KMHDH841CMKU915909

DATE : 26/1/2021

SUPPLEMENTARY ESTIMATE :

1SET FRONT NO. PLATE
1PC. NO. PLATE GARNISH
1PC. BUMPER SPOONGE

*He new
Cracked
Cracked*

\$	45.00	SN	X
\$	32.80		
\$	131.80		
\$	209.60		

164.60

Supplementary: 131.68

