

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 4 Jan 2021

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN3111X

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$145.00 / SCR
1 pc	• Front wheel shaft	\$75.00 ? XSVL
1 pc	Left front foot rest	\$75.00 / BT
1 pc	Front left fork assy	\$680.00 XSVL
1 pc	Side stand	\$85.00 / SCR
1 pc	• Steering stem	\$220.00 X600 ? / BT
1 pc	• Steering bridge	\$195.00 X600 / BT
2 pcs	• Steering bearings	\$90.00 X300 ? - NEC
1 set	Gear pedal	\$78.00 / BT
1 pc	Front left signal	\$125.00 / MIS
1 pc	Left view mirror	\$95.00 / SCR
1 pc	• IU bracket	\$45.00 X200 ? / BT
1 pc	• Handle bar	\$175.00 X130 ? / BT
1 pc	Left balancer	\$48.00 / MIS
1 pc	Clutch lever	\$55.00 / SCR
1 pc	Left handgrip	\$35.00 / TIN
1 pc	Fuel tank left cover	\$205.00 / SCR
1 pc	Fuel tank emblems	\$75.00 / NEC
1 pc	Left rear signal	\$115.00 / SCR
1 pc	• Left side cover emblem	\$40 \$70.00 / NEC
1 pc	• Left side cover	\$140 \$175.00 / SCR CRX
		1,941
		\$2,861.00
	Less discount 10%	\$286.10
		\$2,574.90
	<u>Special nett items</u>	
1 pc	• Sport rim front	\$450 \$580.00 / CHIPPED
1 pc	• Front number plate	\$20.00 / BT
1 pc	ERP IU	\$627 \$157.00 / BR
1)	Towing charges	SEPARATE \$100.00 X
2)	Replace, realign and adjust above damaged parts, check wiring and lighting system	\$800.00 300
3)	To knock, straighten chassis & body balancing	\$380.00 XVIN
4)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00 XVIN
•	To remove/refit, replace (if damage) check and straighten front sport rims.	\$150.00 50
4)	Spray painting	\$280.00 200
6)	Total Estimate	<u>\$5,221.90</u>

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 CLK
6/11/2021 1500

LIS

3 DAYS

(CHECK FROM PHOTOS)

AFTER REPAIR PHOTOS



BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
 ROC/ GST Reg No.: 200007407G

Date: 8 Jan 2021


SUPPLEMENTARY FOR REPAIR: YAMAHA XABRE TFX150 - FBN3111X

Chassis No.:
 Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Headlamp assy	\$350 \$365.00 - CRK
1 pc	Headlamp bracket	\$150 \$175.00 - BT
1 pc	Left front foot rest holder	\$165.00 - BT
1 pc	Left clutch holder	\$75.00 - BT
1 pc	Clutch switch (side stand)	\$65.00 - BR
1 pc	Left signal switch assy	\$140 \$195.00 - CRK
		9.15 <u>\$1,040.00</u>
		<u>\$104.00</u>
	Less discount 10%	\$936.00
	Special nett items	
1 pc	Front tyre	\$580.00 X SVC
1)	Labour for removing and replacing supplementary parts	<u>\$150.00</u> \$70
	Total Estimate	<u><u>\$1,666.00</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

PARTS \$2,886.00
 LESS 10% \$2,597.40
 SINEFF \$ 627.00
 LABOUR \$ 620.00
 TOTAL \$3,844.40
 LESS LIS 20% \$3,075.52
 LIS TOTAL \$3,100.00 / 3 REPAIR DAYS


 For Bike Production Pte Ltd