

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 4 Jan 2021

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN3111X

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
		\$145.00 /scr
1 pc	Front fender	\$75.00 ?
1 pc	Front wheel shaft	\$75.00 /BT
1 pc	Left front foot rest	\$680.00 xxx XSVL
1 pc	Front left fork assy	\$85.00 /scr
1 pc	Side stand	\$220.00 xxxx
1 pc	Steering stem	\$195.00 xxx /BT
1 pc	Steering bridge	\$90.00 xxx ?
2 pcs	Steering bearings	\$78.00 /BT
1 set	Gear pedal	\$125.00 /MIS
1 pc	Front left signal	\$95.00 /scr
1 pc	Left view mirror	\$45.00 xxx ?
1 pc	IU bracket	\$175.00 PF ?
1 pc	Handle bar	\$48.00 /MIS
1 pc	Left balancer	\$55.00 /scr
1 pc	Clutch lever	\$35.00 /TN
1 pc	Left handgrip	\$205.00 /scr
1 pc	Fuel tank left cover	\$75.00 /NEC
1 pc	Fuel tank amblems	\$115.00 /scr
1 pc	Left rear signal	\$70.00 NEC
1 pc	Left side cover amblem	\$175.00 2 /scr
1 pc	Left side cover	
		<hr/>
		\$2,861.00
		\$286.10
		<hr/>
		\$2,574.90
	<u>Special nett items</u>	
1 pc	Sport rim front	\$580.00 /CHIPPED
1 pc	Front number plate	\$20.00 /BT
1 pc	ERP IU	\$157.00 /BR
1)	Towing charges	\$100.00 X
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$800.00 300
	To knock, straighten chassis & body	
3)	balancing	\$380.00 XNN
	To remove/refit, replace (if damage) check and	
4)	straighten front fork tubes.	\$180.00 XNN
	To remove/refit, replace (if damage) check and	
4)	straighten front sport rims.	\$150.00 50
6)	Spray painting	\$280.00 200
	Total Estimate	<hr/>
		\$5,221.90

Note: The above estimate is subjected to the prevailing GST of 7%

NA2 UKK
6/11/2021 1500

L15

3 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

