



Mercedes-Benz

CYCLE & CARRIAGE INDUSTRIES PTE LTD

MERCEDES BENZ CENTER

301 ALEXANDRA ROAD, SINGAPORE 159968

FAX : 68661601 TEL : 68661600

Date : **07/01/2021**

Attention : Kuek Ju Huat

Dear Sir / Mdm

ESTIMATED COST OF REPAIRS

REGISTRATION NO :SFK6800P MODEL : Mercedes-Benz GLA180 SPORT UTILITY WDC1569422J6856240

We have inspected on the above vehicle and found that the following jobs will have to be carried out:

S/No	Repairs Required (Labour and Materials)	\$
1	ENGINE WIRING HARNESS	\$1,300.00
2	LABOUR FOR REPLACE ENGINE WIRING HARNESS	\$1,300.00
	Estimate Total (Excluding 7%GST)	\$2,600.00

The total estimated cost as stated above is **\$2,600.00**. Estimated costs quoted are excluding 7% GST.

We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work

Please sign below on the duplicate copy of this estimate and return same with 50% deposit to us if you agree to the above.

Jack Teo

Vincent lai

Name:

Executive Service Advisor

Name:

Customer Service Advisor

I, _____ owner/owner's representative agree to the above and hereby authorize **Cycle & Carriage Industries Pte Ltd** to carry out the work. I also agree to pay full amount for renewal of the windscreen in the event of inadvertent brakeage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature: _____

Date: _____