

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
 Blk 8 , Kaki Bukit Avenue 4 , #02-24
 Premier @ Kaki Bukit Singapore 415875
 Email: claims@rico60.com
 Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Lump Sum	
ERV	

TO: MSIG
 Vehicle No : SLU 4533 A
 Make & Model : HONDA VEZEL
 DATE: 5/1/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE <i>95330.60 ✓</i>	1	\$ 1,050.00	\$ 1,050.00
2	TAILGATE WINDSCREEN MOULDING <i>nei ✓</i>	1	\$ 198.00	\$ 198.00
3	TAILGATE WINDSCREEN INNER SEAL <i>nei ✓</i>	1	\$ 50.00	\$ 50.00
4	TAILGATE EMBLEM(VEZEL) <i>nei ✓</i>	1	\$ 89.00	\$ 89.00
5	TAILGATE STOPPER <i>nm x</i>	2	\$ 25.00	\$ 50.00
6	TAILGATE INNER TRIM <i>175.50. de ✓</i>	1	\$ 477.60	\$ 477.60
7	TAILGATE POCKER HANDLE <i>nm x</i>	1	\$ 98.60	\$ 98.60
8	TAILGATE INNER LOCK <i>180. btz ✓</i>	1	\$ 665.00	\$ 665.00
9	TAILGATE LOCK CATCH <i>nm x</i>	1	\$ 46.00	\$ 46.00
10	TAILGATE WEATHERSTRIP <i>108-60. fm ✓</i>	1	\$ 298.40	\$ 298.40
11	TAILGATE LOCK DETECTOR <i>nm x ✓</i>	1	\$ 317.90	\$ 317.90
12	TAIL LAMP <i>460.60 LHeng ✓ RHM ✓</i>	2	\$ 582.40	\$ 1,164.80
13	REAR BUMPER <i>549.20 de ✓</i>	1	\$ 598.50	\$ 598.50
14	REAR BUMPER SIDE RETAINER <i>cm ✓</i>	2	\$ 120.00	\$ 240.00
15	REAR BUMPER SIDE GARNISH <i>m ✓</i>	2	\$ 255.50	\$ 511.00
16	REAR BUMPER REFLECTOR <i>cm ✓</i>	2	\$ 120 177.90	\$ 240 355.80
17	END PANEL <i>415.60. bt ✓</i>	1	\$ 511.90	\$ 511.90
18	END PANEL TOP TRIM <i>101-60. de ✓</i>	1	\$ 288.70	\$ 288.70
19	REAR ALARM BUZZER <i>120. cm ✓</i>	1	\$ 321.10	\$ 321.10
20	REAR FLOOR PANEL <i>Rp ✓</i>	1	\$ 896.50	\$ 896.50
21	REAR FLOOR PANEL TOP BOARD <i>285 de ✓</i>	1	\$ 376.50	\$ 376.50
22	REAR FLOOR PANEL TOOL SPONGE <i>327.20 de ✓</i>	2	\$ 165.60 411.10	\$ 822.20
23	STOP START BATTERY <i>X.n. ✓</i>	1	\$ 650.00	\$ 650.00
24	REAR FENDER INNER TRIM <i>RH de ✓ LH de ✓</i>	2	\$ 344.20 470.00	\$ 688.40 940.00
25	REAR FENDER INNER SHIELD <i>tn ✓</i>	2	\$ 149.80 198.70	\$ 299.60 397.40
26	REAR FENDER ARCH GARNISH <i>de ✓</i>	2	\$ 195 255.90	\$ 390 511.80

	REAR EXHAUST SILENSER	Ry	1	\$ 658.00	\$ 658.00
8	REAR EXHAUST MOUNTING		2	\$ 50.00	\$ 100.00
9	REAR EXHAUST GASKET	X nu } X	1	\$ 45.00	\$ 45.00
30	REAR EXHAUST HEAT PLATE		1	\$ 217.00	\$ 217.00
31	Rear Bumper Lower Cover	del	1	250.379.00	379.00

6632.60.
20% 5306.08

Subtotal : \$ 12,946.70
Less 20% \$ 2,589.34
Parts Total : \$ 10,357.36

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
13	REAR WINDSCREEN SEALANT <i>new 60.</i>	1	\$ 80.00	\$ 80.00
14	TAILGATE INNER TRIM CLIP <i>new 20</i>	1	\$ 40.00	\$ 40.00
17	REAR BUMPER CLIP <i>new 30.</i>	1	\$ 50.00	\$ 50.00
18	END PANEL SEALANT <i>40 new</i>	1	\$ 80.00	\$ 80.00
19	END PANEL TOP TRIM CLIP <i>10 new</i>	1	\$ 30.00	\$ 30.00
20	REAR FLOOR PANEL SEALANT <i>X nu</i>	1	\$ 80.00	\$ 80.00
21	REAR FENDER INNER TRIM CLIP <i>10 new</i>	1	\$ 50.00	\$ 50.00
22	REAR FENDER INNER SHIELD CLIP <i>10 new</i>	1	\$ 40.00	\$ 40.00
23	REAR FENDER ARCH GARNISH CLIP <i>10 new</i>	1	\$ 40.00	\$ 40.00
24	REVERSE SENSOR <i>200 new</i>	1	\$ 450.00	\$ 450.00
				<i>390.</i>
				\$ 940.00

LABOUR (REAR)		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	<i>800</i>	\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	<i>1000</i>	\$ 1,600.00
TO PERFORM LIGHTING & WIRING CHECK	<i>30</i>	\$ 150.00
TO APPLY ANTI-RUST & TUFF KOTE	<i>30.</i>	\$ 150.00
REMOVE AND INSTALL REAR WINDSCREEN	<i>120</i>	\$ 150.00
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART	<i>60.</i>	\$ 150.00
REMOVE, INSTALL AND CHECK REVERSE SENSOR	<i>30</i>	\$ 150.00
REMOVE AND INSTALL CARPET, TRIM AND INTERRIOR	<i>60.</i>	\$ 200.00
REMOVE AND INSTALL REAR EXHAUST	<i>X</i>	\$ 150.00
<i>Remove battery for repair work.</i>	<i>- 200.</i>	<i>\$ 450.</i>
	<i>2330.</i>	
LABOUR TOTAL		\$ 4,500.00

Total Parts Cost	\$	11,297.36
Total Labour Cost	\$	4,500.00
Total Repair Cost	\$	15,797.36

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Taphin 97495747
 'wp' 6/1/24 @ 1230
 4/5 Resurvey after repair
 Taphin @ 11hants-on
 06 days.

5306-08
 390
 2330

 8026-08

4/5 @ 6400
 06 days #

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: