

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

4-Jan-21

Our ref : TP/4926/21

HockHua Tonic Pte Ltd

TP China
Xiao Tong
VSKYBAM2020137979

RE : estimate cost for vehicle no : GBH 6185U

1 pc	rear lh door <i>Dented</i>	\$	1,469.60	nett ✓
1 pc	NV 200 emblem <i>new</i>		141.70	✓
2 pcs	rear lh door hinges <i>new</i>		230.00	+
1 pc	rear lh door outer handle <i>Dented</i>		352.00	168.50
1 pc	Nissan emblem <i>new</i>		64.90	✓
1 pc	wiper arm <i>new</i>		89.00	+
1 pc	wiper motor <i>Dented</i>		310.80	✓
1 pc	rear lh door top lock <i>new</i>		115.00	+
1 pc	rear lh door lower lock <i>Jammed</i>		115.00	✓
2 pcs	rear no plate lamp <i>new</i>		160.40	+
1 pc	rear lh door trimboard <i>Dented</i>		220.00	193.
10 pcs	rear lh door trimboard clips <i>new</i>		51.00	20
1 pc	rear lh door rubber <i>cut</i>		168.70	✓
1 pc	rear lh door w/strip <i>new</i>		111.00	+
1 pc	rear rh door <i>Dented</i>		1,102.00	✓
2 pcs	rear rh door hinges <i>new</i>		230.00	+
1 pc	rear rh door rubber <i>cut</i>		106.00	✓
1 pc	rear rh door trimboard <i>new</i>		145.00	+
10 pcs	rear rh door trimboard clips <i>new</i>		51.00	+
1 pc	rear rh door top lock <i>new</i>		115.00	+
1 pc	rear rh door lower lck <i>Jammed</i>		115.00	✓
2 pcs	taillamp <i>cracked</i>		554.00	✓
1 pc	rear bumper <i>Dented</i>		632.70	✓
2 pcs	rear bumper reflector <i>cracked</i>		123.80	✓
2 pcs	rear bumper retainers <i>new</i>		84.00	✓
10 pcs	rear bumper clips <i>new</i>		51.00	30
1 pc	rear bumper sponge <i>Dented</i>		94.00	✓
1 pc	rear bumper tow hook cover <i>new</i>		21.40	+
1 pc	end panel inner <i>Dented</i>		776.00	✓
1 pc	end panel outer <i>Dented</i>		511.00	345
1 pc	spare tyre tray <i>cut</i>		421.00	252
1 pc	spare tyre screw <i>new</i>		21.40	+
1 pc	exhaust pipe <i>new</i>		552.00	+
1 pc	floorboard panel <i>Rps</i>		1374.60	+
			<u>10680.00</u>	

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921

Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RE : estimate cost for vehicle no : GBH 6185U

Bal brought forward:

\$

10,680.00

1 pc floorboard panel inner garnish *del*
10 pcs floorboard panel inner garnish clips *new*
less 10%

175.70 ✓

~~51.00~~ 20

10,906.70

1,090.67

9816.03

7042.40
6338.16

1 pc rear lh door Co logo *NEC*
1 pc 70 km/h sticker *new*
1 pc 6 pax sticker *new*
1 pc reverse sensor *Don't*
1 pc rear no plate *Bed*
1 pc camera *Don't*
1 pc rear lh door gum *new*
1 pc rear rh door gum *new*

~~400.00~~ *sniff* 280

~~25.00~~ 10

~~25.00~~ 10

~~250.00~~ 200

30.00 ✓

~~400.00~~ 350

50.00 ✓

50.00 ✓

~~1,800.00~~ 1200

~~1,500.00~~ 1200

30.00 ✓

~~100.00~~ 60

~~100.00~~ 60

~~80.00~~ 60

~~80.00~~ 60

80.00 ✓

14816.03

1037.12

15853.15

Panel beating.

Spray painting.

Wiring.

Remove & refit rh door glass.

Remove & refit lh door glass.

Transfer rh door parts.

Transfer lh door parts.

Remove & refit exhaust pipe.

Plus 7% GST

SD : Fifteen thousand eight hundred fifty-three & cents fifteen only.

Adrian L
4/5 05/01/21

1 pc ply wood
CmLd

400 SN

200

~~250~~ (SN).

09 Days.

total: 10238.16