

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

02/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chim.
Justin.

Accident date: 31/12/2020

Estimated repair cost for vehicle no: SLQ2381E SUBARU FORESTER 2.0I-L CVT '17

CHASSIS: JF1SJ5KC5HG092435

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$1,192.30	✓
2	2	Rear Boot Lid Hinge <i>Not new</i>	\$55.00	\$110.00	X
3	2	Rear Boot Lid Shock Absorber <i>Not new</i>	\$154.00	\$308.00	X
4	1	Rear Boot Lid Emblem Logo <i>new</i>		\$65.00	✓
5	1	Rear Boot Lid Subaru Logo <i>new</i>		\$68.00	X
6	1	Rear Boot Lid Forester Logo <i>new</i>		\$68.00	✓
7	1	Rear Boot Lid AWD Logo <i>new</i>		\$65.00	✓
8	1	Rear Boot Lid Number Plate <i>Not new</i>		\$50.00	X
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$560.30	264
10	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$160.30	✓
11	1	Rear Boot Lid Inner Trim Board <i>cracked</i>		\$220.30	✓
12	10	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00	30
13	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$85.00	40
14	2	Rear Boot Lid Windscreen Side Seal <i>new</i>	\$75.00	\$150.00	40
15	1	Rear Boot Lid Reverse Camera <i>new</i>		\$850.00	X
16	2	Rear Tail Lamp <i>cracked</i>	\$437.30	\$874.60	✓
17	2	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$16.00	✓
18	1	Rear L/H Tail Lamp Panel <i>Paint</i>		\$105.80	X
19	1	Rear L/H Tail Lamp Lower Bracket <i>cracked</i>		\$38.00	✓
20	1	Rear Bumper <i>cracked</i>		\$980.30	600
21	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
22	1	Rear L/H Bumper Side Retainer <i>new</i>		\$38.00	✓
23	1	Rear L/H Bumper Side Reflector <i>cracked</i>		\$42.00	✓
24	1	Rear Bumper Towing Cover <i>cracked</i>		\$22.00	✓
25	1	Rear L/H Bumper Exhaust Cover <i>cracked</i>		\$76.80	✓
26	1	Rear Bumper Reinforcement <i>Best</i>		\$320.80	✓
27	2	Rear Bumper Reinforcement Bracket <i>new</i>	\$28.60	\$57.20	X

28	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dangd</i>		\$380.00	<i>2w/sr</i>
29	1	Rear L/H Fender <i>Repis</i>		\$1,060.40	<i>x</i>
30	2	Rear Fender Inner Trim Board <i>Dehnd</i>	\$486.30	\$972.60	<i>684</i>
31	8	Rear Fender Inner Trim Board Clip <i>nu</i>	\$6.50	\$52.00	<i>✓</i>
32	1	Rear End Panel <i>Distorted</i>		\$332.00	<i>✓</i>
33	1	Rear End Panel Top Garnish <i>Dehnd</i>		\$90.00	<i>✓</i>
34	1	Rear Spare Tyre Panel <i>Distorted</i>		\$632.40	<i>✓</i>
35	1	Rear Spare Tyre Panel Top Cover <i>Dehnd</i>		\$336.00	<i>✓</i>
36	1	Rear Spare Tyre Panel & End Panel Sealant <i>HEM</i>		\$450.00	<i>x</i>
37	2	Rear Spare Tyre Panel Side Foam Tool Box <i>culd</i>	\$85.50	\$171.00	<i>✓</i>
38	1	Rear Spare Tyre Panel Foam Tool Box <i>culd</i>		\$161.20	<i>✓</i>
39	1	Rear Centre Exhaust <i>HEM</i>		\$1,048.40	<i>x</i>

*Rees Exhaust Muffler
Dangd*

7349.70

688

Subtotal :-

\$12,339.70

5879.76

S.N: 2w

Labour charges

To remove & refit cushion & trim board

\$280.00 100

To remove & refit reverse sensor

\$100.00 50

To remove & refit reverse camera

\$180.00 50

To remove & refit rear windscreen

\$150.00 12w

To remove & refit rear exhaust

\$200.00 80

Gum

\$60.00 ✓

To check wiring

2980

\$100.00 30

Tuff kote

\$150.00 80

Panel beating

\$2,400.00 12w

Spray painting

\$2,000.00 1200

Subtotal :-

\$5,620.00

Total:-

\$17,959.70

Supplementary: 940

total: 9989.76

A/S: 8K 09hpy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

8K

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

04/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 31/12/2020

Supplementary repair cost for vehicle no: SLQ2381E SUBARU FORESTER 2.0I-L CVT '17

CHASSIS: JF1SJ5KC5HG092435

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Center Moulding <i>ganish. Here</i>		\$260.30
2	1	Rear Bumper Top Subaru Moulding (Special Nett) <i>cracked</i>		\$480.00 <i>300(SN)</i>
3	1	Rear Spare Tyre Panel Foam <i>cracked</i>		\$90.00 ✓
4	1	Rear Spare Tyre Lock Foam		\$85.00 ✓

Subtotal :- \$915.30

Labour charges

Ceramic Coating

Subtotal :- \$1,200.00

Total:- \$2,115.30

Supplementary: 940



3mendous (S) Pte Ltd



INVOICE

No. 6367

DATE 9 OCT 2017 ATTENDED BY: JACK

Detailer: JACK / LIM / WATA

Name Tay Yong Meng

VEHICLE NO: 8LQ 2381 E

Ferry: Y / N

Address

H/P:

Res:

Off:

Vehicle Details:

Make & Model: SUBARU FORESTER

Colour: BROWN


Reg. Date:

Capacity: 1700cc 1700cc 1700cc SECTION

Saloon / Coupe / MPV / SUV / Cabriolet: ROMC

Recommended By:

Remarks:



PPS POMPONAZI GLASS COATING 24 MONTH

\$ 1800/-

Others

\$

Balance Payable:

\$ 1800/-

I/We hereby acknowledge that my car was handed over to 3MENDOUS (S) PTE LTD with the imperfections highlighted above. I/We fully understands that the said company shall not be responsible for all pre-existing imperfections although all professional care and attention will be provided to try eventually cure or minimise. 3MENDOUS (S) PTE LTD shall not be held responsible for any monies, valuables, ornaments or souvenirs should they be found missing and I/We am/are fully aware that it is my/our own responsibilities to ensure there wasn't any valuables in the vehicle.

 DATE IN: 9 OCT 2017
TIME IN:

 DATE OUT: 9 OCT 2017
TIME OUT:

Authorised

Authorised

www.ppstechnology.com

3mendous (S) Pte Ltd
1 Bukit Batok Crescent #04-30 WCEGA Plaza Singapore 658064
Tel: +65 6316 3771, +65 6316 3772
andy@3mendouss.com