

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

02/01/2021

Blk C 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP1st Cap.
Justin.

Accident date: 31/12/2020

Estimated repair cost for vehicle no: SMC1437Y NISSAN NOTE 1.2 A '18

CHASSIS: JN1TAAE12Z0980582

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bonnet <i>Buckled.</i>		\$847.80 ✓
2	2	Front Bonnet Hinge <i>new</i>	\$35.00	\$70.00 X
3	2	Front Headlamp <i>cracked</i>	\$1,614.60	\$3,229.20 ✓
4	2	Front Headlamp Lower Bracket <i>new</i>	\$28.10	\$56.20 X
5	1	Front Grille <i>cracked</i>		\$276.70 ✓
6	1	Front Grille Emblem Logo <i>new</i>		\$29.10 ✓
7	1	Front Grille Top Cover <i>cracked</i>		\$194.40 ✓
8	1	Front Grille Lower Chrome <i>cut</i>		\$180.00 ✓
9	1	Front Grille Lower Garnish <i>new</i>		\$155.00 X
10	1	Front Bumper <i>Distorted</i>		\$394.30 ✓
11	2	Front Bumper Side Retainer <i>new</i>	\$35.20	\$70.40 ✓
12	2	Front Bumper Fog Lamp Cover <i>new</i>	\$130.20	\$260.40 X
13	1	Front Bumper Towing Cover <i>ded</i>		\$29.20 ✓
14	1	Front Bumper Inner Foam <i>cracked.</i>		\$219.00 ✓
15	1	Front Bumper Reinforcement <i>Best</i>		\$495.00 381.60
16	2	Front Bumper Reinforcement Bracket <i>new</i>	\$94.80	\$189.60 X
17	1	Front Support Panel <i>cracked.</i>		\$315.80 ✓
18	1	Front Support Panel Top Cover <i>new</i>		\$276.70 X
			Subtotal :-	<u>\$7,288.80</u>

*6167.50.
5550.75*

S/n	Qty	Items / Special Nett	U/price	Amount
19	8	Front Grille Clip <i>new</i>	\$6.50	\$52.00 20
20	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
21	1	Front Bumper Number Plate <i>new</i>		\$50.00 X
22	1	Front Air-Con Condenser <i>Best</i>		\$655.00 ✓
23	1	Front Radiator <i>Distorted</i>		\$689.60 ✓
24	1	Front Radiator Fan Motor Assy <i>cracked</i>		\$891.40 ✓

2286.60
2057.40

Subtotal :- \$2,403.00

Labour charges

To remove & refit air-con condenser, radiator, fan motor, & top up gas	\$280.00	120
Towing fee	\$150.00	60
Tuff kote	\$150.00	1
To check wiring	\$100.00	30
Panel beating	\$2,000.00	700
Spray painting	\$1,400.00	600

Subtotal :- \$4,080.00

Total:- \$13,771.80

Tolud: 9/18/15
H/S: 7.3K.
06 Days.

7.3K
06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: