



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102385

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 09/04/2021
Reference CC4/FCI21000180/Uea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SDR 5665G
Insured Veh. SHB 4707M
Claim No. D21000129MFSH
Policy No. D-20094921MFSH
Accident Date 31/12/2020
Inspection Date 07/01/2021

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21000180/Uea3q2	
			Date: 09/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4707M	Veh. Inspected	SDR 5665G	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D21000129MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	05/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHFC1660GT000559	Colour	BLACK	
Odometer	63916 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	235/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	235/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	235/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2020	Inspection Date	07/01/2021	
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDR 5665G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEEP CUT	579.90	579.90
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	14.70	-
1	FRONT BUMPER FOG LAMP GRILLE RH	SCRATCHED	29.90	29.90
1	FRONT FENDER SIGNAL LAMP	SCRATCHED	38.10	38.10
1	FRONT HEADLAMP ASSY RH	NOT NECESSARY	1,118.70	-
	LESS 20% DISCOUNT		-356.26	-129.58
			1,425.04	518.32
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER LOWER SPOILER (SN)	CRACKED	500.00	500.00
			500.00	500.00
	<u>LABOUR</u>			
	REMOVE & INSTALL F/GRILLE ,F/HEADLAMP ,F/BUMPER,KNOCK F/FENDER AND RESTRAIGHTEN BODY.		280.00	250.00
	SPRAY PAINTING .		500.00	400.00
	CHECK WIRING SYSTEM.		25.00	20.00
			805.00	670.00
GRAND TOTAL			2,730.04	1,688.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CC4/FCI21000180/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDR 5665G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SDR 5665G

RE-INSPECTION

