

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SDR 56656

at Workshop m/s

NPH

of

Insured:

SHB 4707M

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$ 78k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 53402

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Dep 11k.

have video at Aldi

13/1/21 2/5 \$1350 confirmed with Ray

Veh No:

SDR 56656

Yr Regn:

25/4/17

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda civic

C.C

1498

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

63916

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC1660GT 000559

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/1/20

D.O.I.

7/1/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Ry.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/2
Our Ref : TP0001/01/21 Date : 04/01/2021

THIRD PARTY CLAIM

M/S : TEO CHONG BENG
115 PASIR RIS GROVE
#06-44
SINGAPORE 518172

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SDR5665G - HONDA CIVIC (A)
INSURED : TEO CHONG BENG
DATE OF ACCIDENT : 30/12/2020
POLICY NO : MP312594

ENGINE# :
CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front bumper	1@	579.90	579.90	579.90 ✓
2 front bumper side retainer RH <i>Deep 47</i>	1@	14.70	14.70	14.70 X
3 front bumper fog lamp grille RH <i>scr</i>	1@	29.90	29.90	29.90 ✓
4 front fender signal lamp <i>scr</i>	1@	38.10	38.10	38.10 ✓
5 front headlamp assy RH <i>scr</i>	1@	1118.70	1118.70	1,118.70 X
6 front bumper lower spoiler <i>\$500 s.w. cra</i>				1,781.30
Less 20%				-356.26
Total Material				\$1,425.04
Labour & Misc				
1 Remove & install f/grille, f/headlamp, f/bumper, knock f/fender and restraighten body. <i>250</i>				280.00
2 Spray painting. <i>400</i>				500.00
3 Check wiring system. <i>20</i>				25.00
Total Labour				\$805.00
Nett Total Before Gst				\$2,230.04

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Arthur
2/5 1350.1
24/1/21
7/1/21

P-647.9
20%
518.32
1688.32