

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

4-Jan-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1029 X

1 pc	Front o/s fender	\$	384.00 <i>bl</i>
1 pc	Front o/s door	\$	765.00 <i>Ry</i>
1 pc	o/s mirror Assy	\$	590.00 <i>Ry X114</i>
		\$	1,739.00
		\$	173.90
		\$	1,565.10

384
10% 345.60 Less 10%

S/NETT

1 pc	Front o/s fender sticker	\$	30.00 <i>nei</i>
1 set	o/s door sticker	\$	100.00 <i>nei</i>
		\$	50.00 <i>nei</i>
	Sundry	\$	150.00 <i>nei</i>
	To dismantle and refit the inner component of front o/s door into new shell door	\$	450.00 <i>200</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s fender, etc	\$	600.00 <i>400</i>
	To putty and spray painting on front o/s fender, front o/s door, o/s side mirror	\$	150.00 <i>30</i>
	To apply rustproofing on the repaired and replaced panels.	\$	3,095.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphui 97495749
WP 4/1/21 2520pm
2 days
4/1 Resurvey after repair
Tanphui C Mantawon