

LKK Admin



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company & GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
 (MOTOR CLAIM DEPARTMENT)

Email claimsdept@sg.cntaiping.com

Asher.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SME 4972M

Date: 05.01.2021

Veh. Model : HYUNDAI ELANTRA AD

Reg. Date : 01.10.2018

Chassis No : KMHD841CMJU757132

1	Front RH Door <i>Dented</i>	1 pc		1,904.70	
2	Front RH Door Switch <i>new</i>	1 pc		14.50	+
3	Front RH Door Outer Handle <i>new</i>	1 pc		188.10	+
4	Front RH Door Outer Handle Bracket <i>new</i>	1 pc		68.50	+
5	Front RH Door Outer Chrome Moulding <i>new</i>	1 pc		93.90	+
6	Front RH Door Lock <i>Damaged new</i>	1 pc		191.50	+
7	Front RH Door Lock Catch <i>new</i>	1 pc		23.10	+
8	Front RH Door Black Sticker <i>new</i>	2 pcs	14.80	29.60	-
9	Front RH Door Hinges <i>lower Bar</i>	2 pcs	59.80	119.60	29.80
10	Front RH Door Weatherstrip <i>lot</i>	1 pc		96.00	-
11	Front RH Door Frame Weatherstrip <i>new</i>	1 pc		119.20	+
12	Front RH Door Inner Trim Board <i>Cracked</i>	1 pc	462	756.90	-
13	Front RH Door Regulator Motor <i>new</i>	1 pc		267.80	+
14	Front RH Door Regulator Gear <i>Damaged</i>	1 pc		280.40	+
15	Front RH Door Channel Seal <i>new</i>	1 pc		140.60	+
16	Front RH Door Stoppers <i>new new</i>	2 pcs	8.60	17.20	+
17	Front RH Door Lock Mechanisms <i>Damaged</i>	1 pc		234.00	-
18	Front RH Door Step Garnish <i>new</i>	1 pc		29.80	+
19	Front RH Door Side Mirror Assy <i>new</i>	1 pc		638.60	+
20	Front Door Pillar (Inner) <i>Damaged</i>	1 pc		498.00	-
21	Center Pillar RH <i>Dented</i>	1 pc	805	3,919.20	+
22	Center Pillar Garnish Top RH <i>new</i>	1 pc		62.50	+
23	Center Pillar Garnish Bottom RH <i>new new</i>	1 pc		55.90	+
24	Front Bumper <i>Repis</i>	1 pc		474.40	+

C/F

10,224.00



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company & GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

B/F

10,224.00

25	Front Fender RH <i>Dented</i>	1 pc	985	1,227.70	✓
26	Front Fender Inner Cowling RH <i>toru</i>	1 pc		85.70	✓
27	Front Fender Mudflap RH <i>New</i>	1 pc		35.00	+
5	Front Shock Absorber RH <i>Best</i>	1 pc		392.50	✓
6	Front Shock Absorber Top Mounting RH <i>New</i>	1 pc		128.90	+
7	Front Lower Arm RH <i>Best</i>	1 pc		296.80	✓
8	Front Knuckle Arm RH <i>Dented</i>	1 pc		363.60	✓
9	Front Wheel Bearing RH <i>New</i>	1 pc		452.80	✓
10	Front Tie Rod	1 pc		116.50	+
11	Front Tie Rod End <i>New</i>	1 pc		73.50	+
12	Front Stabilizer Bar	1 pc		246.80	+
13	Front Stabilizer Bar Linkage <i>New</i>	1 pc		75.50	+
14	Rear Bumper <i>Repair</i>	1 pc		459.40	✓
15	Rear RH Door <i>Dented</i>	1 pc	1575	1,878.30	✓
16	Rear RH Door Outer Handle <i>New</i>	1 pc		68.80	+
17	Rear RH Door Chrome Outer Moulding <i>New</i>	1 pc		85.10	+
18	Rear RH Door Black Sticker <i>New</i>	3 pcs	14.80	44.40	✓
19	Rear RH Door Lock <i>New</i>	1 pc		191.50	+
20	Rear RH Door Lock Catch <i>New</i>	1 pc		23.10	+
21	Rear RH Door Hinges <i>Best Lones</i>	2 pcs	59.80	119.60	59.80
22	Rear RH Door Weatherstrip <i>lot</i>	1 pc		116.20	✓
23	Rear RH Door Frame Weatherstrip <i>New</i>	1 pc		105.80	+
24	Rear RH Door Inner Trim Board <i>Cracked</i>	1 pc	738	613.60	✓
25	Rear RH Door Stoppers <i>New</i>	2 pcs	8.60	17.20	+
26	Rear RH Door Regulator Motor <i>New</i>	1 pc		267.80	+
27	Rear RH Door Regulator Gear <i>New</i>	1 pc		280.40	✓
28	Rear RH Door Channel Seal <i>New</i>	1 pc		140.60	+
29	Rear RH Door Checker <i>New</i>	1 pc		78.30	+
30	Rear RH Door Step Garnish <i>New</i>	1 pc		29.80	+
31	Side Rocker Panel RH <i>Dented</i>	1 pc		1,799.60	✓
32	Rear Fender RH <i>Repair</i>	1 pc		1,892.00	+

C/F

21,930.80



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company & GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

B/F **21,930.80**

1	Rear Shock Absorber RH <i>3 pc</i>	1 pc		230.50	+
2	Rear Wheel Bearing RH <i>3 pc</i>	1 pc		454.00	+
3	Sport Rims <i>6 pc</i>	2 pcs	671.30	1,342.60	✓
				23,957.90	
				Less 20%	4,791.58
				<b>19,166.32</b>	

*12825.50*  
*10260.40*

**Special nett item**

1	Front Bumper Clips <i>new + m</i>	1 set		50.00	+
2	Front Fender Inner Cowling Clips <i>new</i>	1 set		30.00	+
3	Rear Bumper Clips <i>new</i>	1 set		50.00	+
4	Rear Fender Inner Cowling Clips <i>new</i>	1 set		30.00	+

*30*

To remove and replace accident affected portion.	<del>2,600.00</del>	<i>1400</i>
To respray accident affected portion.	<del>2,800.00</del>	<i>1600</i>
To tuff coat affected areas.	<del>200.00</del>	<i>100</i>
To apply sealant and under coating to the affected areas.	<del>250.00</del>	<i>100</i>
To conduct wiring check.	<del>80.00</del>	<i>30</i>
To conduct water leak test.	120.00	<i>+</i>
To remove and replace both doors parts	<del>360.00</del>	<i>180</i>
To remove and replace front & rear undercarriage.	<del>600.00</del>	<i>220</i>
To perform wheel alignment check.	<del>180.00</del>	<i>80</i>
To remove and refit RH interior upholstery.	<del>280.00</del>	<i>80</i>
To perform reset on the power window module and setting	160.00	<i>+</i>
To reset and reprogram fault code.	<del>180.00</del>	<i>100</i>
<b>27,136.32</b>		

*TRK Auto Consultants hence notify*  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*3870*

*Adrian Lj*  
*2/s 06/01/21*  
*11 Days*  
*total: 14160.40*  
*1/s: 11.3K*

*12.2K*