



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG WEE HONG, JASON (HUANG WEIFENG) 88 MULBERRY AVENUE SINGAPORE 348417 Contact No Mobile: 91885380	Cust No/Name	KCV15313/NG WEE HONG, JASON (HUANG WEIFE
	Reg No/Reg Date	SKL3881K / 21/01/202
	Date In/Mileage	/ 0
	Chassis No	GF7W0602232
	Engine No	4J11BN1023
	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	30/12/2020/ 11:55	QUE	261 / Edwin Caina	61306			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3200.00
RENEW RR BUMPER & BODY KIT								
REPAIR LHR FENDER & RR END PNL								
E PNT98000								2200.00
RESPRAY RR BUMPER , RR BUMPER BODY KIT , LHR FENDER & RR END PNL								
A 54900099								80.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								100.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								280.00
SUPPLY REVERSE SENSOR								
M SUNDRY								80.00
SUPPLY BODY KIT SEALANT								
M SUNDRY								120.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								50.00
Sundries								
M REFLECTOR, TAIL LAMP, LH					1.00	100.00	00.00	100.00
M LAMP ASSY, COMB, RR LH					1.00	600.00	00.00	600.00
M FACE, RR BUMPER					1.00	807.00	00.00	807.00
M REINFORCEMENT, RR BUMPER, LH					1.00	79.00	00.00	79.00
M EXTENSION, RR BUMPER					1.00	292.00	00.00	292.00
M BRKT, R/BMPR FACE SIDE, LH					1.00	12.00	00.00	12.00
M MOULDING, RR BUMPER, LH					1.00	88.00	00.00	88.00
M MOULDING, RR WHEEL ARCH, LH					1.00	168.00	00.00	168.00
M BODY KIT, OUTLANDER					1.00	1554.00	00.00	1554.00
SURVEYOR NAME : _____								

Confirm & accepted by SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Authorized signatory and company stamp

Nett	10,090.00
7% GST on	10090.00
	706.30
Total Payable	10,796.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/12/2020 16:49 (SGT)
Date of Accident	28/12/2020 04:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Along Bartley Road just before Gambir Walk turning.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL3881K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG WEE HONG
NRIC No	S8619237C
Email Address	JAZONNS.NG@GMAIL.COM
Mobile Phone No	(Phone) +65-91885380
Alternative Phone No	+65-82335151

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	TP CLAIM
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2000003330
Cover Note Number	-

DRIVER

Name of Driver	NG WEE HONG
NRIC No	S8619237C
Date Of Birth	18/06/1986

Occupation	Indoor
Date Of Driving Pass	06/10/2018
Driving experience	2 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91885380
Alt. Phone Number	+65-82335151
Email Address	JAZONNS.NG@GMAIL.COM
Address	88 MULBERRY AVENUE
Address complement	SINGAPORE
Postcode	348417
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Zonia Tan
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

R2000006900 Circumstances Of Accident SKL3881K was driving along Woodleigh Underpass towards Gambir Walk and had the left indicator light turned on for at least 50m prior to the turn-in into Gambir Walk. 3881K saw 5253D stationary at the stop line along Bartley Road and hence proceeded to make the turn into Gambir Walk. Upon making the turn into Gambir Walk

3881 was knocked at the left rear. Both drivers got out of the car

where 5253D apologised profusely for the accident especially when 3881K had 2 children (1 baby and 1 toddler onboard)

exchanged contacts and took pictures of the damages.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA5253D-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	(Phone) +65-96706108
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

