

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance

Date 4/1/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLR374J

CHASSIS NO : GP71046200

MAKE / MODEL : Honda Shuttle Hybrid 1.5 CVT

DATE OF ACCIDENT : 01/01/2021

YOUR INSURED VEHICLE NUMBER : SLT9759M

MILEAGE : 128380 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / ON	1PC	\$ 1,850.00	\$ 1,850.00 1,210
2	Rear tailgate lock / Jam	1PC	\$ 550.00	\$ 550.00 200
3	Rear tailgate lock catch X SVC	1PC	\$ 158.00	\$ 158.00 X
4	Rear tailgate windscreen moulding / NCC	1PC	\$ 195.00	\$ 195.00 /
5	Rear tailgate weatherstrip / CMY	1PC	\$ 255.00	\$ 255.00 /
6	Rear tailgate holder cover X SVC	1PC	\$ 80.00	\$ 80.00 X
7	Rear tailgate Honda emblem X SVC	1PC	\$ 81.30	\$ 81.30 X
8	Rear tailgate shuttle emblem / NCC	1PC	\$ 88.40	\$ 88.40 /
9	Rear tailgate Hybrid emblem / NCC	1PC	\$ 83.00	\$ 83.00 /
10	Rear bumper / CMY	1PC	\$ 1,350.00	\$ 1,350.00 1,100
11	Rear bumper LH side retainer / P/B/R	1PC	\$ 128.00	\$ 128.00 /
12	Rear bumper RH side retainer X SVC	1PC	\$ 128.00	\$ 128.00 X
13	Rear bumper LH reflector garnish cover / SCR	1PC	\$ 178.00	\$ 178.00 /
14	Rear bumper LH reflector X SVC	1PC	\$ 250.00	\$ 250.00 X
15	Rear bumper sponge X SVC	1PC	\$ 150.00	\$ 150.00 X
16	Rear end panel X R	1PC	\$ 1,200.00	\$ 1,200.00 X
17	Rear end panel top cover ? X SVC	1PC	\$ 300.00	\$ 300.00 X
18	Rear bumper tow cover X SVC	1PC	\$ 30.00	\$ 30.00 X
19	Rear antenna sensor ? X SVC	1PC	\$ 200.00	\$ 200.00 X
LIST TOTAL S\$:				\$ 7,254.70 3,437.40
20.00% DISCOUNT S\$:				\$ 1,450.94 -20%
				\$ 5,803.76 2,749.92

SPECIAL NETT

1	Reverse sensor	short	1 SET	\$ 260.00	200
2	Windscreen sealant	MEC	1 SET	\$ 120.00	40
3	Body Sealant	X SVC	1 SET	\$ 300.00	X
4	Bumper clips	MEC	1 SET	\$ 120.00	30
5	End panel to garnish clips	X SVC	1 SET	\$ 80.00	X
Special Nett Total S\$:				\$ 880.00	270

LABOUR CHARGES

1	TO REMOVE REAR TAILGATE ,REAR BUMPER, END PANEL OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND ALSO STARIGHTEN SPARE TYR PANEL INCLUDE CUTTING/WELDING OF DAMAGED PARTS	\$ 1,000.00	750
2	TO RESPRAY REAR ROOF SPOILER,REAR TAILGATE, REAR BUMPER, END PANEL AND SPARE TYRE PANEL(INNER/OUTER)	\$ 1,200.00	800
3	TO REMOVE & INSTALL REAR WINDSCREEN	\$ 160.00	120
4	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS.	\$ 80.00	40
5	TO TRANSFER TAILGATE MECHANISM	\$ 100.00	60
6	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST REPAIRS DIAGNOSTIC SCAN TEST AS AREQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	\$ 300.00	X NN

LABOUR TOTAL S\$:	\$ 2,840.00	1770
TOTAL S\$:	\$ 9,523.76	
7% GST	\$ 666.66	
GRAND TOTAL S\$:	\$ 10,190.42	

Repair dy - 4 days

LIS

After pain photo

Sun Pin (LHK)

05/01/2021

TP with prepdu

2,749.92
 270
 1,770
 4,789.92
 - 20%
 3,831.94

LIS
 \$ 3,850
 4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: