



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2106900

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 05/10/2021  
Reference CC6/CTI21000190/Kra3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLW 4961L  
Insured Veh. YP 7060A  
Claim No. SNM21D200074/LKKDS  
Policy No. DMCVSNW00050622001  
Accident Date 04/01/2021  
Inspection Date 12/01/2021

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21000190/Kra3q2	
			Date: 05/10/2021	
			Code: CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	YP 7060A	Veh. Inspected	SLW 4961L	
Policy No.	DMCVSNW00050622001	Coverage (\$)	0.00	
Claim No.	SNM21D200074/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	12/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN QASHQAI (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	SJNFBAJ11U2164886	Colour	METALLIC GREY	
Odometer	56788 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R19	DUNLOP	5 mm	
L/H Front Tyre	225/45 R19	DUNLOP	5 mm	
R/H Rear Tyre	225/45 R19	DUNLOP	4 mm	
L/H Rear Tyre	225/45 R19	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	04/01/2021	Inspection Date	12/01/2021	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 4961L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SIDE MIRROR ,LH (N) }	CRACKED	611.50	1,734.20
1	MIRROR COVER (N) }	MISSING	141.10	-
1	FRONT FENDER ,LH (N)	BENT	622.70	622.70
1	FRONT BONNET (N)	BENT	1,855.00	1,054.30
1	BUMPER RETAINER (N)	SERVICEABLE	35.90	-
1	FENDER COWLING (N)	SERVICEABLE	101.90	-
1	COWLING CLIP (N)	NOT NECESSARY	38.00	-
	LESS 10% DISCOUNT		-340.61	-341.12
			3,065.49	3,070.08
	<b><u>LABOUR</u></b>			
	TO REMOVE DAMAGED PARTS N ATTACHMENTS REPAIR ALL DENTED AREAS REPLACE ABOVE PARTS.		700.00	400.00
	TO REMOVE DOORBOARD ,DOOR MOULDING ,REPLACE SIDE MIRROR ,RECTIFY WIRING .		80.00	20.00
	TO SPRAY PAINT .		750.00	480.00
			1,530.00	900.00
	<b>GRAND TOTAL</b>		<b>4,595.49</b>	<b>3,970.08</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,970.08</b>

Report Ref No. CC6/CT121000190/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLW 4961L**

**INSPECTION**







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLW 4961L**

**RE-INSPECTION**

