

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

08,Jan 2020

China Taiping Insurance (S) PI
105 Cecil Street
#18-00
The Octagon
S 069534

Attn: motor claim dept-3rd party claim

Claiming against your insured vehicle no: YP7060A

Accident involving vehicle no: SLW4961L/YP7060A

DOA: 04/01/2021 AT Yinhun Avenue 1 turning into Sembawang Rd

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SLW4961L

To supply--

Description	Qty	Amount
Side mirror,Lh	1	611.50 N
Mirror cover	1	141.10 N
Front fender,Lh	1	622.70 N
Front bumper	1	1,855.00 N
Bumper retainer	1	35.90 N
Fender cowl	1	101.90 N
Cowling clip		38.00 N
Parts		3,406.10
Parts less 10%		340.61
		3,065.49

To remove damaged parts n attachments

Repair all dented areas

Replace above parts

To remove doorboard,door moulding,replace side mirror,rectify wiring.

To spray paint

700.00

80.00

750.00

4,595.49

400
20
480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Attached
Returning After 4 days

3970.08