

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1026/2020/NS
DATE : 30-Dec-20
WIP : 64789

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

4 days - ok - jb - 8 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR WU XI
ADDRESS : 6 LINCOLN ROAD
#06-12
SINGAPORE 308345
TELEPHONE : HP +65 93896800
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800109327-02
VEHICLE NO : **SMD 9481 K**
MODEL CODE : AUDI A5 SPOTBACK 2.0 TFS
MODEL YEAR : 12/9/2018
ENGINE NO : CVK 064975
CHASSIS NO : WAUZZZF56JA116607
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Dec-20
PLACE OF ACCIDENT : ALONG CTE BETWEEN BRADDELL AND AMK AVE 1

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 9481 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET AND HINGES.	\$	2,700.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,172.00	\$ 2,772.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 7945 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,251.00	\$ 1,800.80
2	FRONT BUMPER FIXING PARTS		\$ 402.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4	FRONT BUMPER GRILLE - CENTRE		\$ 194.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 225.00	
6	FRONT BUMPER AIR GUIDE - RH		\$ 62.00	
7	RADIATOR GRILLE		\$ 2,300.00	\$ 1,840.00
8	ULTRASOUND SENSOR SUPPORT - LH/RH	2	\$ 102.00	
9	RADIATOR GRILLE COVER - UPPER		\$ 187.00	
10	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 468.00	
11	FRONT BUMPER CARRIER		\$ 795.00	\$ 636.00
12	FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	\$ 99.20
13	FRONT BUMPER GUIDE SECTION - RH		\$ 36.00	
14	FRONT BUMPER TOP COVER		\$ 126.00	\$ 101.60
15	CAUTION SIGN STICKER	NEC	\$ 14.00	\$ 10.88
16	AIRCON STICKER	NEC	\$ 8.00	\$ 5.68
17	LOCK CARRIER BRACKET		\$ 136.00	\$ 109.60
18	LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$ 56.00	\$ 44.96
19	HORN - RH LOW TONE		\$ 124.00	
20	SPRING SHACKLE - RH		\$ 29.00	
SUB TOTAL SPARE PARTS		:	\$ 7,708.00	\$ 4,648.72

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 9481 K

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES		
			S/NETT	REMARKS	
		<i>c/f</i>		\$	4,648.72
21	FRONT PARKING AID SENSOR - INNER/OUTER	2	\$ 484.00		
22	FRONT PARKING AID SEAL RING	4	\$ 14.00		
23	BONNET		\$ 2,817.00	\$	2,253.60
24	BONNET ATTACHMENT PARTS		\$ 121.00		
25	BONNET LID HINGE - LH/RH	2	\$ 830.00		
26	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$	21.84
27	BONNET IMPACT PROTECTION - LH		\$ 28.00	\$	22.00
28	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$	21.84
29	BONNET SOUND ABSORBER		\$ 339.00		
30	BONNET STRIKER - RH		\$ 50.00		
31	BONNET LID LOCK		\$ 212.00		
32	BONNET BOWDEN CABLE - CENTRE		\$ 57.00		
33	BONNET RELEASE LEVER		\$ 13.00		
34	BONNET LOCK CABLE		\$ 57.00		
35	LED HEADLIGHT - RH		\$ 7,812.00		
36	LIFT CYLINDER - RH		\$ 196.00		
37	LIFT CYLINDER CORRUGATED PIPE - RH		\$ 85.00		
38	RADIATOR AIR GUIDE - OUTER		\$ 31.00		
39	RADIATOR AIR GUIDE - INNER		\$ 16.00		
40	RADIATOR AIR GUIDE - UPPER		\$ 16.00		
SUB TOTAL SPARE PARTS		:	\$ 13,232.00	\$	6,968.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 9481 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
			<i>c/f</i>
			\$ 6,968.00
41 RADIATOR AIR GUIDE - LOWER		\$ 22.00	
42 FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
43 SUNDRIES		\$ 250.00	\$ 17.12
TOTAL SPARE PARTS	:	\$ 21,272.00	\$ 7,045.12
TOTAL LABOUR CHARGES	:	\$ 6,172.00	\$ 2,772.00
GRAND TOTAL	:	\$ 27,444.00	\$ 9,817.12

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-10/02/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT