

Car-in

1/2/21

mp: 64789

kiam / kang



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. ~~SLO 7843~~ SMD 9481 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>Rehnd</i>		\$	2,251.00	✓
2 FRONT BUMPER FIXING PARTS <i>Neu</i>		\$	402.00	+
3 FRONT BUMPER SECURING STRIP <i>Neu</i>	2	\$	70.00	+
4 FRONT BUMPER GRILLE - CENTRE <i>Neu</i>		\$	194.00	+
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Neu</i>		\$	225.00	+
6 FRONT BUMPER AIR GUIDE - RH <i>Neu</i>		\$	62.00	+
7 RADIATOR GRILLE <i>cracked</i>		\$	2,300.00	✓
8 ULTRASOUND SENSOR SUPPORT - LH/RH <i>Neu 2</i>		\$	102.00	+
9 RADIATOR GRILLE COVER - UPPER ?		\$	187.00	?
10 FRONT BUMPER AIR GUIDE GRILLE - RH <i>Neu</i>		\$	468.00	+
11 FRONT BUMPER CARRIER <i>Dented.</i>		\$	795.00	✓
12 FRONT BUMPER FOAM FILLER PIECE <i>cracked.</i>		\$	123.00	✓
13 FRONT BUMPER GUIDE SECTION - RH <i>Neu</i>		\$	36.00	+
14 FRONT BUMPER TOP COVER <i>cracked</i>		\$	126.00	✓
15 CAUTION SIGN STICKER ?	NEC	\$	14.00	✓
16 AIRCON STICKER <i>Neu</i>	NEC	\$	8.00	✓
17 LOCK CARRIER BRACKET <i>cracked.</i>		\$	136.00	✓
18 LOCK CARRIER BRACKET SUPPORT - LH/RH <i>Rph2</i>		\$	56.00	✓
19 HORN - RH LOW TONE <i>Neu</i>		\$	124.00	+
20 SPRING SHACKLE - RH <i>Neu</i>		\$	29.00	+
SUB TOTAL SPARE PARTS		:	\$	7,708.00

Adrian King
AS