



# ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E  
Email: alfredauto@hotmail.com

Tyre &  
Sports Rim



**Reference No.: 20121**

**Date:** 2.1.2021

**Yeo Poh Tin**

**16 Windsor Park Road**

**Singapore 574125**

**Range Rover Velar 2.0S 14R**

**Estimate Repair Cost for Vehicle Reg. No: SGZ 1200 M**

1 Pc. Front Bumper		3,123.00
1 Pc. Front Bumper Side Retainer		39.00
2 Pcs. Front Bumper Parking Sensor	@ 312.00	624.00
10 Pcs. Front Bumper Clips	@ 6.00	60.00
1 Pc. Front Fender		1,170.00
1 Pc. Front Fender Dust Garnish		388.00
10 Pcs. Front Fender Dust Garnish Clips	@ 5.50	55.00
1 Pc. Front Head Lamp Assy (LH)		3,510.00

---

**Total (Panels / Parts): 8,969.00 (SGD)**

**LABOR CHARGES**

To check wiring.	120.00
To repair & renew all accident affected damage area & straightening damage area.	800.00
To respray painting on all accident damage affected area. (2 color)	900.00
To rust proof all accident affected area.	150.00
To diagnostic all accident sensors & erase fault code.	180.00
To check computer wheel alignment & camber, castor.	180.00

---

**Total (Labor Charges): 2,330.00 (SGD)**



# ALFRED AUTO

## Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E  
Email: alfredauto@hotmail.com



### TOTAL COST SUMMARY

PANELS / PARTS	8,969.00
LABOR CHARGES	2,330.00

---

**Grand Total: 11,299.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to '**Alfred Auto Services and Supplies**'

*Alfred Quah*

---

**ALFRED AUTO SERVICES & SUPPLIES**

**[WITHOUT PREJUDICE SAVE AS TO COSTS]**