



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 06/01/21
LHK - STEVE

VEHICLE NO : SGP 5005L

MODEL : MIT/ECLIPSE cross 1.5 T/C

WIP : 61489

Material	:	\$	<u>2,356.97</u>
Labour	:	\$	<u>2,400.00</u>
Sub-Total	:	\$	<u>4,756.97</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>800.00</u>
Total	:	\$	<u>3,956.97</u>
GST 7%	:	\$	<u>276.99</u>
Grand Total	:	\$	<u>4,233.96</u>

Re-Finalise By/Date : Larry on 21/01/21

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV16183/GOH KENG SWEE Reg No/Reg Date SGP5005L / 29/10/2020 Date In/Mileage 06/01/2021/ 5607 Chassis/Package JMAXTGK1WLZ001714 /DC17PT Engine No 4B40HM9006 Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR (T33) Colour/Trim D00 LIGHTNING BLUE / BK BLACK
06/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/01/2021/ 09:21	BLE	884 / Lauro Songcuan	61489

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RH FRONT DOOR & RH REAR DOOR, REPAIR RH REAR FENDER ARC				900.00 ✓
E PNT98000 SPRAY RH FRONT DOOR, RH REAR DOOR & RH REAR FENDER				1050.00 ✓
E PNT88000 REMOVE & REFIT RH FRONT DOOR COMPONENTS				120.00 ✓
E PNT88000 REMOVE & REFIT RH REAR DOOR COMPONENTS				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00 ✓
KAS USING HI-SCAN PRO TEST				
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
X EXC EXCESS				-800.00
X PANEL ASSY,FR DOOR,RH	1.00	949.00	23.00	730.73 ✓
X MOULDING,F/DR SASH,UPR RH	1.00	119.00	23.00	91.63 ✓
X PANEL ASSY,RR DOOR,RH	1.00	937.00	23.00	721.49 ✓
X MOULDING,R/DR SASH,UPR RH	1.00	114.00	23.00	87.78 ✓
X MOULDING,R/DOOR PROTECT,RH	1.00	105.00	23.00	80.85 ✓
X GARNISH,FR DOOR,RH	1.00	* 241.00	23.00	185.57 ✓
X GARNISH,RR DOOR,RH	1.00	* 160.00	23.00	123.20 ✓
X SIDE EXTENSION → Supp	1.00	436.00	23.00	335.72 X
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 06.01.2020 DOA: 05.01.2021 05 DAYS				
* change price				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	2,356.97	Nett	3,956.97
Labour	2,340.00	7% GST on	276.99
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	4,233.96
Sundry/Others	-740.00		
Total(w/o GST)	3,956.97		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SGP 5005 L

<u>Materials</u>			<u>Cost \$</u>
1	Side Extension		
		CUT	436.00
	23% Discount		100.28
			<u>335.72</u>
	7% GST		23.50
	Total		<u>359.22</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SGP5005LWIP: 61489 (ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	MOULBING, RR WHEEL HUB, RH	(?) SUPP			
2	BODYKITS MOULBING RR - RHR DOOR	? / SUPP	<i>Stu</i>	<i>✓ CUT</i> <i>(Back) ✓ CUT</i>	OS
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	<i>4.09.11</i>	DATE	TAKEN BY
PHOTO AFTER PAINT		<i>8/11/11</i>	<i>Stu</i>
PHOTO OF MOUNT TO CELLETTE BENCH			
REMOVE AND INSTALL ENGINE			
REMOVE AND INSTALL DASHBAORD			
REMOVE & INSTALL FUEL TANK			
PHOTO UNDERCARRIAGE PARTS			

MODEL: ECLIPSESURVEYOR: STEVE

All DTCs

SGP50051
Before using PAOT-3x you want to check all the sensors

2021.01.12

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	GK1W 2020MY

All DTCs

2021.01.12

All DTCs

2021.01.12

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
CORNER SENSOR/SONAR	SONAR_9D080000		No DTCs		
ACC/FCM	ACCSCFCM_4B080004		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100	B2547	RH side view CAMERA fault	Stored	
EPB	EPB_4C080000		No DTCs		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		No DTCs		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		
HUD	HUD_9E080000		No DTCs		

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	GK1W 2020MY

SGP50051
 After using MUT-3, not wait for ECU all the bond
 to be done.

2021.01.12

All DTCS

2021.01.12

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0C640000		No DTCS	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCS	
4WS/Electric Power Steering	EPS_45840000		No DTCS	
ABS/ASC/ASTC/MSS	ASC_42080014		No DTCS	
SRS-AIR BAG	SRS_81047305		No DTCS	
Air Conditioner	AC_80080017		No DTCS	
ETACS	ETACS_83040800		No DTCS	
TPMS (with KOS)	ETACS_83040800		No DTCS	
Meter	METER_84088001		No DTCS	
Steering Angle Sensor	GS_SAS_47000100_Forum3		No DTCS	
AUDIO (IntelligentDisplay)	AUDIO_8D080002		No DTCS	
LIN	ETACS_83040800		Non-target System	
KOS/OSS/MMO/Keyless (with KOS)	ETACS_83040800		No DTCS	

All DTCs

2021.01.12
