



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/1040/2020/NS
DATE	:	4-Jan-21
WIP	:	65236

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	PREMIUM AUTOMOBILES PTE LTD
ADDRESS	:	55 UBI ROAD 1
	:	SINGAPORE 408699
TELEPHONE	:	OFF +65 68365223
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	999993763/100877789/00000
VEHICLE NO	:	SMN 9189 C
MODEL CODE	:	AUDI TT COUPE 2.0 TFSI S
MODEL YEAR	:	30/8/2019
ENGINE NO	:	CHH 310224
CHASSIS NO	:	TRUZZZFV9K1009836
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	29-Dec-21
PLACE OF ACCIDENT	:	20 OLD LIM CHU KANG RD SINGAPORE 708976

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMN 9189 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER	S/N \$ 360.00 ✓	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00 500 ✓	✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00 1100 ✓	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>3,952.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMN 9189 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 3,032.00	crq ✓ 2614.40
2 FRONT BUMPER CLOSING ELEMENT - LH		\$ 110.00	? X nn
3 FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 248.00	mis ✓ 200.00
4 FRONT REINFORCEMENT BEAM		\$ 977.00	X nn
5 FRONT BUMPER FOAM FILLER PIECE		\$ 188.00	X nn
6 LED HEADLIGHT - LH		\$ 7,836.00	cm ✓ 6340.80
7 LIFT CYLINDER - LH broken		\$ 157.00	? 127.20
8 LIFT CYLINDER BRACKET - LH missing		\$ 29.00	? 23.20
9 LIFT CYLINDER HOSE - LH		\$ 76.00	? X nn
10 FRONT PARKING AID SENSOR - OUTER		\$ 242.00	mis ✓ 193.60
11 FRONT PARKING AID SEAL RING	4	\$ 14.00	req ✓ 11.20
12 AUDI EMBLEM		\$ 122.00	req ✓ 110.00
13 SUNDRIES		\$ 250.00	? 1.92 nec
TOTAL SPARE PARTS	:	\$ 13,281.00	
TOTAL LABOUR CHARGES	:	\$ 3,952.00	
GRAND TOTAL	:	\$ 17,233.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanfu 97495749.

5/1/20 @ 1520.

Not Authorise

Ex: to be advise

tanfu @ lkh auto.com.
04 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

PR. 245 / 40R18.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT